


 A Renesas Company	ISL6614CBZA-T
	Manufacturer Part Number: ISL6614CBZA-T
	Manufacturer/Brand: Intersil
	Part of Description: IC DRIVER DUAL SYNC BUCK 14-SOIC
Datasheets:  ISL6614CBZA-T.pdf	RoHS Status:  Lead free / RoHS
Stock Condition: Compliant New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL6614CBZA-T
Manufacturer	Intersil
Description	IC DRIVER DUAL SYNC BUCK 14-SOIC
Category	Integrated Circuits (ICs) > PMIC - Gate Drivers
Part Status	Require For Quote & Check Stock
Series	-
Input Type	Non-Inverting
Operating Temperature	0°C ~ 125°C (TJ)
Mounting Type	Surface Mount
Package / Case	14-SOIC (0.154", 3.90mm Width)
Supplier Device Package	14-SOIC
Voltage - Supply	10.8 V ~ 13.2 V
Channel Type	Synchronous
Driven Configuration	Half-Bridge
Number of Drivers	4
Gate Type	N-Channel MOSFET
Logic Voltage - VIL, VIH	-
Current - Peak Output (Source, Sink)	1.25A, 2A
Rise / Fall Time (Typ)	26ns, 18ns
High Side Voltage - Max (Bootstrap)	36V
Packaging	Tape & Reel (TR)

ISL6614CBZA-T is New Original in Stock, Search ISL6614CBZA-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6614CBZA-T Intersil with warrantied and confidence. RFQ ISL6614CBZA-T : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL6614CBZ-TR5238 Intersil IC DRVR DUAL SYNC BUCK 14-SOIC	 ISL6614CBZR5238 Intersil IC DRVR DUAL SYNC BUCK 14-SOIC	 ISL6614CBZ-T Intersil IC DRIVER DUAL SYNC BUCK 14-SOIC	 ISL6614CR-T Intersil IC DRIVER DUAL SYNC BUCK 16-QFN
 ISL6614CBZ Intersil IC DRIVER MOSF DUAL SYNC 14SOIC	 ISL6614CRZ Intersil IC DRIVER MOSF DUAL SYNC 16QFN	 ISL6614CBZ-TR5214 Intersil IC DRVR DUAL SYNC BUCK 14-SOIC	 ISL6614CBZA Intersil IC DRIVER DUAL SYNC BUCK 14-SOIC

Hot Parts

More

- | | | | | |
|------------------------|----------------------|-------------------|--------------------|--------------------|
| ⊕ 08055C104J4T2A | ↔ 18127C473KAT2A | ⇒ 362 638/5 47/02 | D ADG609BR | ↔ AL1696-30AS7-13 |
| ⊖ AL1697-20CS7-13 | ⊕ AM29F160DB-75ED | D AP1084D25G-13 | ⇒ AP60T03GP | ↔ AT45DB/SP081D-SU |
| ⊕ AVR-M1005C080MTAABG | ⊖ BCP49-E6327 | ⊕ BU24590-8H | ↔ BZT52H-C56 | ↔ CD8446R1CBM |
| D CM30TF-24E | ⊕ DD200KB220 | ⊖ DD260N14 | ⊕ FDC6329L | ↔ FDP050AN06AO |
| ⇒ GLFR1608T100M-LRHF | ↔ GRM1886T1H111JD01D | ⊕ HAT2099H02-EL | ⊖ IXTH88N30 | ↔ JFW150F1 |
| ↔ LMSZ5225BT1G | ⇒ LTC4416EMS | D M306V7MJA-061FP | ⊕ MAX986EUK+T | ⊖ MB1519PF |
| ⊕ MB85RC16VPNF-G-JNERE | D MC10H131FNR2 | ⇒ NGD15N41ACLT4G | ↔ PFS714EG | ↔ PT1202E23E-ADJ |
| ⊖ R9G20114CJ00 | ⊕ SAM40150D | ↔ SIHFR020T-E3 | ⇒ SKMD40F04 | ↔ SKND81/04 |
| ⊕ SKY65227-11 | ⊖ SMT6303D | ⊕ STB200N4F3 | D STK795-523 | ↔ TM150SA-18 |
| ↔ TND011NM | ⊕ UMK063CG390JT-F | ⊖ UPA821TF-T1 | ⊕ UPD70F3044YGC-ZU | ↔ Z85C3010VSC |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited