

 Not Actual Photo YIC International Co., Limited.	<b>MD54-0003</b>
	<p><b>Manufacturer Part Number:</b> MD54-0003</p> <p><b>Manufacturer/Brand:</b> MACOM</p> <p><b>Part of Description:</b> MACOM SOP8</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 1200 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
Image may be representation. See specs for product details.	





### Specifications

Part Number	MD54-0003
Manufacturer	MACOM
Description	MACOM SOP8
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1200 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MD54-0003 is New Original in Stock, Search MD54-0003 Datasheets, PDF, Inventory at Y-IC.com Online, Order MD54-0003 with warranted and confidence. RFQ MD54-0003 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>MD53U50</b> MD MD SOT-89	 <b>MD53U30</b> MD MD SOT-89	 <b>MD54-0005TR</b> MA/COM MA/COM SOT23-5	 <b>MD53R50</b> MD MD SOT23-5
 <b>MD54-0004TR</b> MACOM MACOM SOP	 <b>MD53R33</b> MD MD SOT23-5	 <b>MD5406</b> N/A N/A QFP44	 <b>MD53U33</b> MD MD SOT-89

### Hot Parts

More

- |                       |                        |                     |                       |                        |
|-----------------------|------------------------|---------------------|-----------------------|------------------------|
| ⚙️ 1812HC681KAT1A     | ➡️ 6RI100G-060         | ➡️ ACPF-7041-TR     | D ACT6360US-T         | ➡️ AP18T10AGH          |
| ⚡ AP8853-28PL         | ⚙️ AT91SAM9R64-CU      | D AT93C86A-10SU-2.7 | ➡️ BSM10GD120DN2E3224 | ➡️ C4532JB2A225M230KA  |
| ⚙️ CLF10040T-2R2N-CA  | ⚡ DCR1576SY52          | ⚙️ DMN61D9UWQ       | ➡️ EXB24AB6C1RX       | ➡️ FM25V02-GTR         |
| D GB75YF120UT         | ⚙️ GRM1555C1H5R8BA01D  | ⚡ HMC190MS8E        | ⚙️ ISL60002CIH325     | ➡️ LM393YDT            |
| ➡️ LM87CIMTX          | ➡️ LPT67F-P2R1-45-1-20 | ⚙️ LT1181ACSW#TRPBF | ⚡ LTC3633EUFD#TRPBF   | ➡️ MAX4835ETT18BD2V+T  |
| ➡️ MAX6364LUT44-TG075 | ➡️ MAX823REUK+T        | D MC100EP51DTR2G    | ⚙️ N600DH15HOO        | ⚡ N74F374D             |
| ⚙️ NE5534DRG4         | D PCMB103T-1R0MS       | ➡️ POC-SP65A        | ➡️ RA203620           | ➡️ RT0603BRD07118KL    |
| ⚡ SIR484DP-T1-E3      | ⚙️ SKKL72/22E          | ➡️ SMF51CA-GS08     | ➡️ SN74HCT32DBLE      | ➡️ SSG100C20           |
| ⚙️ STK419-110         | ⚡ T115N06BOC           | ⚙️ T529N12TOF       | D TMK107ABJ225KA-T    | ➡️ TPS2042BQDRQ1       |
| ➡️ TPS77715PWR        | ⚙️ VI-264-CU/F2        | ⚡ VI-910187         | ⚙️ VI-J32-CX-01       | ➡️ VLS252012HBX-2R2M-1 |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited