


	SG1544J-883B
	Manufacturer Part Number: SG1544J-883B
	Manufacturer/Brand: Microsemi
	Part of Description: IC SUPERVISOR 2.5V 25MA 18-JDIP
	Datasheets:  SG1544J-883B.pdf
	RoHs Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS








Specifications

Part Number	SG1544J-883B
Manufacturer	Microsemi
Description	IC SUPERVISOR 2.5V 25MA 18-JDIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	Military, MIL-STD-883
Operating Temperature	-55°C ~ 125°C (TA)
Mounting Type	Through Hole
Type	Power Supply Monitor
Package / Case	18-DIP
Supplier Device Package	18-DIP
Output	Open Drain or Open Collector
Reset	-
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	2.5V
Packaging	Tube

SG1544J-883B is New Original in Stock, Search SG1544J-883B Datasheets, PDF, Inventory at Y-IC.com Online, Order SG1544J-883B Microsemi with warrantied and confidence. RFQ SG1544J-883B : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SG1543J 1328+ SG1543J 1328+</p>	 <p>SG1544J/883B MS MS DIP</p>	 <p>SG1548J-DESC Microsemi IC PWR FAULT MON QUAD 16JDIP</p>	 <p>SG1532L SG-LCC SG1532L SG-LCC</p>
 <p>SG1544J-DESC Microsemi IC SUPERVISOR 2.5V 25MA 18-JDIP</p>	 <p>SG1536 SG SG1536 SG</p>	 <p>SG1548J Microsemi IC PWR FAULT MON QUAD 16JDIP</p>	 <p>SG1544J SG SG1544J SG</p>

Hot Parts

More

- | | | | | |
|--------------------|----------------------|------------------|---------------------|-------------------|
| 0201ZC102MAT2A | 06035A271KAT2A | 1206B106K250CT | D 1206GA820KAT1A | 24LC128T-I/MNY |
| APT2X60DQ120J | BA7810HFP-TR | D BL1117C-33 | BZD27C33P-HE3-08 | CL05C620JB5NCNC |
| CMSH1-40M | CR150DM-16R | DT400N08KOF | HD155122FEB | ICSS12MLF |
| D IMP809LEUR/T | IRF730AS | IRKL42/14S90 | ISL6594ACRZ | LMS1487IMX/NOPB |
| LP2989IMM-5.0/NOPB | LTC4085EDE#PBF | LTC8043FN8 | MAX870EUK/ABZN | MBM29LV160TE-90NC |
| MNR18E0APJ680 | MP03TT580-18 | D NNCD13DA-T1-AT | PIC24FJ16MC102-I/SS | PK55HB-120 |
| RP1205-25GBR | D SAFSF1G44AA0T00R12 | SIRA00DP-T1-GE3 | SKY77336-21 | SMCJ12A-E3/57T |
| SMDJ10CA | SMF16A-GS08 | SN65HVD3080EDGSR | TCUT1600X01 | TMK316B3335KL-T |
| TMP-5/5-12/1-D48 | TOP249EN | TS27L2BIDT | D V24A48H400B3 | V300B28T250A3 |
| VE-J21-01 | VSKT56/14P | WG20035SP | X5043S8-2.7 | XC9572XL-10CSG48I |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited