

	<h2 style="color: red;">X4163V8I-4.5A</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">X4163V8I-4.5A</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Intersil</a>
	<b>Part of Description:</b>	IC SUPERVISOR CPU 16K EE 8-TSSOP
<b>Datasheets:</b>	 <a href="#">X4163V8I-4.5A.pdf</a>	
<b>RoHs Status:</b>	Contains lead / RoHS non-compliant	
<b>Stock Condition:</b>	New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		









### Specifications

Part Number	<a href="#">X4163V8I-4.5A</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC SUPERVISOR CPU 16K EE 8-TSSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	8-TSSOP
Output	-
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.62V
Packaging	Tube

X4163V8I-4.5A is New Original in Stock, Search X4163V8I-4.5A Datasheets, PDF, Inventory at Y-IC.com Online, Order X4163V8I-4.5A Intersil with warrantied and confidence. RFQ X4163V8I-4.5A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>X4165P-2.7A</b> Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p><b>X4163V8-4.5A</b> Intersil IC SUPERVISOR CPU 16K EE 8-TSSOP</p>	 <p><b>X4165PI</b> Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p><b>X4163V8-2.7A</b> Intersil IC SUPERVISOR CPU 16K EE 8-TSSOP</p>
 <p><b>X4163V8I-2.7</b> Intersil IC SUPERVISOR CPU 16K EE 8-TSSOP</p>	 <p><b>X4165P</b> Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p><b>X4163V8I</b> Intersil IC SUPERVISOR CPU 16K EE 8-TSSOP</p>	 <p><b>X4163V8I-2.7A</b> Intersil IC SUPERVISOR CPU 16K EE 8-TSSOP</p>

### Hot Parts

[More](#)

- |   |  |   |   |   |
|---|--|---|---|---|
|  2055-30-SM-RPLF       |  6MBP20RH060            |  7MBP75RA120-55            |  D ACMD-7409        |  ACPM-5002             |
|  AK60C-048L-050F20G    |  AM26LV32EIDR           |  D C0603X6S0G334M030BC     |  => CBK-0515DFE     |  => CDR105B-470LC      |
|  CGA9P1X7S3D103M250KE  |  AK60C-048L-050F20G     |  CGB3B3JB1E474K055AB       |  => DFLT48A-7-F     |  => DRV8303DCAR        |
|  D DZT491-13           |  EP1C12F324I7           |  AK60C-048L-050F20G        |  => FDP047AN08A0    |  => FM25V05-G          |
|  => GA342DR7GF102KW02L |  => GRM1885C1H152FA01D  |  => GRM188B11H182KA01D     |  AK60C-048L-050F20G |  => GRM21BR70J106ME76L |
|  => GRM31A5C3A100JW01D |  => GRM32ER61C476ME15K  |  D HAF1004-90S             |  => HIN211CAS       |  AK60C-048L-050F20G    |
|  => HMC470ALP3         |  D IMC1210ER820K        |  => IPP65R380C6            |  => IRF7102TR       |  => IXTH160N10T        |
|  AK60C-048L-050F20G    |  => LS404CDT            |  => MIC2940A-5.0BT         |  => NCP15XW223J03RC |  => NSR0320MW2T3G      |
|  => PVC150A-8-A        |  AK60C-048L-050F20G     |  => SG-636SCE-34.500000MHZ |  D SQD100N03-3M2L   |  => SS60J7M6P          |
|  => ST303C08LHK3       |  => TFSC06054125-2113A1 |  AK60C-048L-050F20G        |  => TML10112        |  => V24A48T300BN3      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited