


	PCF8562TT/2,118
	Manufacturer Part Number: PCF8562TT/2,118
	Manufacturer/Brand: NXP Semiconductors / Freescale
	Part of Description: IC LCD DRIVER 32/128SEG 48-TSSOP
Datasheets:  PCF8562TT/2,118.pdf	RoHS Status:  Lead free / RoHS
Stock Condition: Compliant New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	PCF8562TT/2,118
Manufacturer	NXP Semiconductors / Freescale
Description	IC LCD DRIVER 32/128SEG 48-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Display Drivers
Part Status	Require For Quote & Check Stock
Series	-
Current - Supply	8µA
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Interface	I ² C, 2-Wire Serial
Configuration	7 Segment + DP, 14 Segment + DP + AP, Dot Matrix
Package / Case	48-TFSOP (0.240", 6.10mm Width)
Supplier Device Package	48-TSSOP
Display Type	LCD
Voltage - Supply	1.8 V ~ 5.5 V
Digits or Characters	8 Characters, 16 Characters
Packaging	Tape & Reel (TR)

PCF8562TT/2,118 is New Original in Stock, Search PCF8562TT/2,118 Datasheets, PDF, Inventory at Y-IC.com Online, Order PCF8562TT/2,118 NXP Semiconductors / Freescale with warrantied and confidence. RFQ PCF8562TT/2,118 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>PCF8562TT/2 NXP PCF8562TT/2 NXP</p>	 <p>PCF8562TT NXP PCF8562TT NXP</p>	 <p>PCF8562TT/S400/2 NXP Semiconductors / Freescale PCF8562TT/S400/2 NXP</p>	 <p>PCF8562DTT/2 NXP PCF8562DTT/2 NXP</p>
 <p>PCF8563BS/4 NXP PCF8563BS/4 NXP</p>	 <p>PCF8562DTT TSSOP PCF8562DTT TSSOP</p>	 <p>PCF8563 NXP PCF8563 NXP</p>	 <p>PCF8562TT/S400/2,1 NXP Semiconductors / Freescale IC LCD DRIVER 48-TSSOP</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|----------------------|------------------------|
| ⊛ 06035A110GAT2A | ↔ 08051A221MAT2A | ⇒ 0805ZC394KAT2A | D 18121C473KAZ2A | ⇒ 5STP27H1600 |
| ⊣ 6DI75A-0J0EXL | ⊛ A3952SLB | D A6250E3R-33 | ⇒ AD7542AD | ⇒ AP061CC3602MR |
| ⊛ AP1084T50L-U | ⊣ BFR182T-GS08 | ⊛ CAT5401JI-10-B1 | ↔ CC0603KRX5R5BB105 | ⇒ CGA2B3X7S2A472K050BB |
| D DM818C-1200-25 | ⊛ GCM1555C1H8R2DA16J | ⊣ GRM0336R1HR30CD01D | ⊛ GRM2195C2A180JZ01D | ⇒ GRM219R61E106MA12D |
| ⇒ GRM55DR72E474KW01L | ↔ HN58X2402SFPIBEZ | ⊛ IP-J54-CZ | ⊣ IP101GRI | ⇒ IRL234STRL |
| ↔ ISL6277HRZ-TR | ⇒ LM4895MMX/NOPB | D LTC490IS8 | ⊛ LXA15T600 | ⊣ M0371YF450 |
| ⊛ M29F400BB55N1 | D MAX9789AETJ+T | ⇒ MAZS3600ML | ↔ MCC72-16 | ⇒ MD16130S-DKM2MM |
| ⊣ MDF5N50FTH | ⊛ MMBT4126LT1G | ↔ SD05-7-F | ⇒ SFH6186-3 | ⇒ SI2302ADS-T1-GE3 |
| ⊛ SI3438DV-T1-E3 | ⊣ SKDT60/12 | ⊛ SN74143N | D SP6669CEK-L/TRR3 | ⇒ SPX1121N-5.0 |
| ↔ TR/3216FF15-R | ⊛ UA7808CK | ⊣ UC3901DW | ⊛ W25Q80DVZPIG | ⇒ WG40045SN |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited