

 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>STR50115</b></p>
	<p><b>Manufacturer Part Number:</b> STR50115</p> <p><b>Manufacturer/Brand:</b> SANKEN</p> <p><b>Part of Description:</b> SANKEN TO5</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 600 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

**Specifications**

Part Number	STR50115
Manufacturer	SANKEN
Description	SANKEN TO5
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	600 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

STR50115 is New Original in Stock, Search STR50115 Datasheets, PDF, Inventory at Y-IC.com Online, Order STR50115 with warrantied and confidence. RFQ STR50115 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p><b>STR51041</b> IC IGBT Modules</p>	 <p><b>STR4A162S</b> Sanken Electric Co., Ltd. IC REG PWM CONV AC/DC 8-SOIC</p>	 <p><b>STR50103</b> IC IGBT Modules</p>	 <p><b>STR50213</b> SK SK TO3P-5</p>
 <p><b>STR50115A</b> SK SK TO3P-5</p>	 <p><b>STR50215</b> SK SK TO3P-5</p>	 <p><b>STR50041</b> IC IGBT Modules</p>	 <p><b>STR50113</b> SK SK ZIP-5P</p>

Hot Parts

More

- |                  |                     |                   |                       |                        |
|------------------|---------------------|-------------------|-----------------------|------------------------|
| ⊕ 04025A0R5DAT2A | ↔ 7447789122        | ⇒ A6821SA-T       | D ADV7310KST          | ⇒ AP7341D-30FS4-7      |
| ⊖ APL1001JX      | ⊕ APM2518N          | D BXA3-24S12-F    | ⇒ C2012X5R1E475K125AB | ⇒ CGJ5K4X7R2H223K130AA |
| ⊕ CIH05Q3N0SNC   | ⊖ CTTF8BGKL00/D     | ⊕ DMTH3004LK3Q    | ↔ ELM9750CAA-S        | ⇒ EPA1885-6            |
| D FODM3022_NF098 | ⊕ FP75R12KT4-B11    | ⊖ FSAC15SH60      | ⊕ GRM1555C2A7R6DA01D  | ⇒ GRM319R71H104JA01D   |
| ⇒ HMC7992LP3DE   | ↔ IXDN409YI         | ⊕ K4E641612D-TC50 | ⊖ LE78D110VC          | ⇒ LM2574M-ADJ          |
| ↔ LT1641IS8      | ⇒ LTC6400CUD-20#PBF | D MAX4330EUK      | ⊕ MAX4695ETC-TG069    | ⊖ MG100H2ZS1           |
| ⊕ MK20DN512VLQ10 | D MP1560DN-Z        | ⇒ PESD3V31UB      | ↔ POT120-02           | ⇒ PRF18BD471QB2RB      |
| ⊖ RT9612BGS      | ⊕ S30814-Q924-X     | ↔ SGA-9189Z       | ⇒ SKKE162/12          | ⇒ SN74ABT16646DLR      |
| ⊕ SN74F126N      | ⊖ STC6602ST6RG      | ⊕ STE36N50A       | D STL115N10F7AG       | ⇒ SW16CXC16C           |
| ↔ SY88982LMGTR   | ⊕ TK11233CUIB-G     | ⊖ TL145406DWR     | ⊕ UPC2749T-E3-A       | ⇒ V24C15T100BG3        |

Contact us: **Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited