

	<h2 style="color: red;">CSTCC8M00G56A-R0</h2>	
	Manufacturer Part Number:	CSTCC8M00G56A-R0
Manufacturer/Brand:	MURATA	
Part of Description:	MURATA SMD-3	
RoHs Status:		
Stock Condition:	New original, 1500 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	CSTCC8M00G56A-R0
Manufacturer	MURATA
Description	MURATA SMD-3
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

CSTCC8M00G56A-R0 is New Original in Stock, Search [CSTCC8M00G56A-R0 Datasheets](#), PDF, Inventory at [Y-IC.com Online](#), Order [CSTCC8M00G56A-R0](#) with warrantied and confidence. RFQ [CSTCC8M00G56A-R0](#) : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>CSTCC8M19G53A-R0 MURATA CSTCC8M19G53A-R0 MURATA</p>	 <p>CSTCC8M00G53A-R0(CSTCC8.00M MURATA CSTCC8M00G53A-R0(CSTCC8.00M MURATA</p>	 <p>CSTCC9M00G53-R0 MURATA CSTCC9M00G53-R0 MURATA</p>	 <p>CSTCC8M00G53A-R0 MURATA CSTCC8M00G53A-R0 MURATA</p>
 <p>CSTCC8M38G53-R0 MURATA CSTCC8M38G53-R0 MURATA</p>	 <p>CSTCC9.83MG0H6-TC MURATA CSTCC9.83MG0H6-TC MURATA</p>	 <p>CSTCC8M00G53-R0/CSTCC8.00MG-TC Original CSTCC8M00G53-R0/CSTCC8.00MG-TC Original</p>	 <p>CSTCC8M00G53-R0 MURATA CSTCC8M00G53-R0 MURATA</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|-----------------------|--------------------|--------------------|----------------------|
| ⚙️ 1812GC331MAT1A | ↔️ 7MBR25SA120-55 | ⇒ A6628SEDT | D AD670JNZ | ⇒ AP4371M-G1 |
| ⊖ ASSR-4128-502E | ⚙️ ATMEGA64A-AU | D BAT54-13-F | ⇒ BAV170E6327 | ⇒ BK2125LM152-T |
| ⚙️ BQ24003RGWRG4 | ⊖ CC1206ZKY5V7BB335 | ⚙️ CL10C471JE8NNNC | ↔️ CL31B475KAHNNNE | ⇒ D350CH26 |
| D DMP32D4S-7 | ⚙️ DPA500F-360 | ⊖ DS1816R-20+T&R | ⚙️ DTC114GKA | ⇒ GRM0336S1E9R3CD01D |
| ⇒ GRM1556P1H5R8CZ01D | ↔️ GRM2195C1H153JA01D | ⚙️ LC89060M | ⊖ LMC7101QM5X | ⇒ LT1076IT-5#PBF |
| ↔️ LTW-110TS5 | ⇒ LX8117-00CDD | D MAX6746KA26+ | ⚙️ MBRS130LT3G | ⊖ MCC170-12I01 |
| ⚙️ MDC26-14IO1 B | D MWI150-17E8T | ⇒ NGTB50N65S1WG | ↔️ PHD11N06LT | ⇒ R8A66950BG#RF1Z |
| ⊖ SKKH161/16 | ⚙️ SKKT90/06D | ↔️ SMK316B7152MF-T | ⇒ SN74F163N | ⇒ SY58052UMG |
| ⚙️ SY88923ALK | ⊖ TC7WG32FC | ⚙️ TDA4916G | D THC63LVDM63A | ⇒ TL431AILPG |
| ↔️ TLE2142AIDRG4 | ⚙️ TPS3110K33DBVR | ⊖ UWT1H100MCL1GB | ⚙️ WM8750BGEFL | ⇒ WS7107CPL |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited