









	<h2 style="color: red;">SC76008A2</h2>
	<p>Manufacturer Part Number: SC76008A2</p> <p>Manufacturer/Brand: TI</p> <p>Part of Description: TI QFN</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 700 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	SC76008A2
Manufacturer	TI
Description	TI QFN
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	700 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

SC76008A2 is New Original in Stock, Search SC76008A2 Datasheets, PDF, Inventory at Y-IC.com Online, Order SC76008A2 with warrantied and confidence. RFQ SC76008A2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SC75B-820 Signal Transformer FIXED IND 82UH 1.03A 370 MOHM</p>	 <p>SC76025A1DCAR TI TI TSSOP48</p>	 <p>SC75B-680 Bel FIXED IND 68UH 1.12A 280 MOHM</p>	 <p>SC7701B SPREADTRU SPREADTRU BGA</p>
 <p>SC75B-820 Bel FIXED IND 82UH 1.03A 370 MOHM</p>	 <p>SC76865DR2 MOTOROL MOTOROL O-NEW S</p>	 <p>SC75B-680 Signal Transformer FIXED IND 68UH 1.12A 280 MOHM</p>	 <p>SC7702A SPREADT SPREADT BGA</p>

Hot Parts More

- | | | | | |
|--------------------|------------------------|----------------------|---------------------------|------------------------|
| ⚙️ 06033D104JAT2A | ➡️ 08053C104K4T2A | ➡️ 1N4752A-T | D AT49BV162A-70CI-A | ➡️ BGB717L7ESD |
| ⊖ BLM41P02PTM00-03 | ⚙️ BSM35GD120DLCE 3224 | D BUZ103S-E3045A | ➡️ BZT52C4V7S-7/0805-4.7V | ➡️ C2012JB1E335K085AC |
| ⚙️ CAT9554WI | ⊖ DMN3024SFG-7 | ⚙️ DS90C383MTDX/NOPB | ➡️ DT1608C-682C | ➡️ F2B4F1GU1 |
| D F930G107MAA | ⚙️ FT2232D-REEL | ⊖ HMC251MS8E | ⚙️ HT82B40R | ➡️ IHLP1616BZER2R2M11 |
| ➡️ IRL3302STRLPBF | ➡️ IS25LP064A-JBLE-TR | ⚙️ LM1267NA | ⊖ LP3865ET-ADJ | ➡️ LT1085CT-3.3 |
| ➡️ MAX211EAI+ | ➡️ MAX706RCSA+ | D MBN1200E17D | ⚙️ MBR3050PT | ⊖ NMC0402X5R104K10TRPF |
| ⚙️ PC87570-ICC/VPC | D PP1R5-5-1515 | ➡️ S29AL032D90TAI040 | ➡️ S3G-13-F | ➡️ SAYEY836MBA0F0AR05 |
| ⊖ SG3000GXH23G | ⚙️ SHS211-63 | ➡️ SKM200GB176D | ➡️ SKY77359-18 | ➡️ SMBJ70CA |
| ⚙️ SMCJ13CA | ⊖ SN65HVD05P | ⚙️ SN74LVC1G11YZPR | D STM32F429ZIT6 | ➡️ TD81F1200KCN |
| ➡️ TLP521-1BL | ⚙️ V300C28T75BN | ⊖ V48A48T500AL | ⚙️ VFC48A12C500AL | ➡️ XC25B57014MR |