

	UPD78F9201	
	Manufacturer Part Number:	UPD78F9201
Manufacturer/Brand:	NEC	
Part of Description:	NEC TSSOP10	
RoHs Status:		
Stock Condition:	New original, 1500 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		









Specifications

Part Number	UPD78F9201
Manufacturer	NEC
Description	NEC TSSOP10
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

UPD78F9201 is New Original in Stock, Search UPD78F9201 Datasheets, PDF, Inventory at Y-IC.com Online, Order UPD78F9201 with warrantied and confidence. RFQ UPD78F9201 : Info@Y-IC.com

You May Be Also Be interested

In:

 UPD78F9200MA(S)-CAC-E1 NEC NEC TSSOP10	 UPD78F9200MA-CAC-A Renesas Electronics America IC MCU 8BIT 1KB FLASH 10SSOP	 UPD78F9202MA-CAC-A Renesas Electronics America IC MCU 8BIT 4KB FLASH 10SSOP	 UPD78F9202MA-S01-CAC-E1 NEC NEC TSSOP-1
 UPD78F9200 NEC NEC TSSOP10	 UPD78F9202MA-CAC-E1-A Renesas Electronics America IC MCU	 UPD78F9189CT-A/JC RENESAS UPD78F9189CT-A/JC RENESAS	 UPD78F9189CT-A/UC NEC NEC DIPPB

Hot Parts

More

- | | | | | |
|----------------------|-------------------------|----------------------|--------------------------|-----------------------|
| ⚙ 6MBP15RZ-060 | ↔ AA51880E | ⇒ B39162-B9474-P810 | D BZV90-C6V2 | ⇒ C2012X8R2A333M125AE |
| ↳ CDRH124NP-100MC | ⚙ CGA2B3X8R1E153K050BD | D CL10C1R2CB8NNND | ⇒ DBS400B18 | ⇒ DM74166N |
| ⚙ DMN4468LSS-13 | ↳ DSEP2*31-06B | ⚙ ESDLIN1524BJ | ↔ F951A476MBAAQ2 | ⇒ FPD12-4.2-48 |
| D GCJ31CR72E104KXJ3L | ⚙ GRM1555C1E6R0DZ01D | ↳ GRM3196S2A390JZ01D | ⚙ HAT3018RJ | ⇒ HV9112NG-G |
| ⇒ IXTA44N15T | ↔ LB1973M-MPB-E | ⚙ LM4050BIM3X-4.1 | ↳ LT1120CN8 | ⇒ LT1129IS8-3.3#TRPBF |
| ↔ LT5512EUF#TRPBF | ⇒ LTC3525ESC6-3.3#TRPBF | D LTC6084HMS8#TRPBF | ⚙ MABA-008937-TC11T5 | ↳ MAZ8056UHL |
| ⚙ MBRA180LT3G | D MC7908CD2TR4G | ⇒ MCP120T-450I/TTS01 | ↔ MLX92213ELD-AAA-000-RE | ⇒ NTD4910NT4G |
| ↳ PE-65738 | ⚙ PIC16F1828I/ML | ↔ PIC16LC54C-04I/SS | ⇒ PIC16LF1509-E/ML | ⇒ R5F3650KCNFB |
| ⚙ S-812C35AUA-C2P-T2 | ↳ SAFFB1G84AB0F0AR15 | ⚙ SMCJ8V0CA | D SMK316BJ153ML-T | ⇒ ST1000C26K0L |
| ↔ TC531000CF | ⚙ TC551001AFI-85L | ↳ TD92N13KOF | ⚙ TPS2062DR-1 | ⇒ XL7001E1 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited