




	<h2 style="color: #E67E22;">MCK500-22IO1</h2>	
	Manufacturer Part Number:	MCK500-22IO1
	Manufacturer/Brand:	IXYS Corporation
	Part of Description:	SCR THYRISTOR CA 2200V WC-500
Datasheets:	 MCK500-22IO1.pdf	
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	

Specifications	
Part Number	MCK500-22IO1
Manufacturer	IXYS Corporation
Description	SCR THYRISTOR CA 2200V WC-500
Category	Discrete Semiconductor Products > Thyristors - SCRs -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TJ)
Mounting Type	Chassis Mount
Structure	Common Cathode - All SCRs
Package / Case	WC-500
Current - Hold (Ih) (Max)	1A
Voltage - Off State	2200V
Voltage - Gate Trigger (Vgt) (Max)	3V
Current - Gate Trigger (Igt) (Max)	300mA
Current - On State (It (AV)) (Max)	545A
Current - On State (It (RMS)) (Max)	1294A
Current - Non Rep. Surge 50, 60Hz (Itsm)	16500A @ 50Hz
Number of SCRs, Diodes	2 SCRs
Packaging	Tray

MCK500-22IO1 is New Original in Stock, Search MCK500-22IO1 Datasheets, PDF, Inventory at Y-IC.com Online, Order MCK500-22IO1 IXYS Corporation with warrantied and confidence.
RFQ MCK500-22IO1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>MCK500-20IO1 IXYS Corporation SCR THYRISTOR CA 2000V WC-500</p>	 <p>MCK500-16IO1 IXYS Corporation SCR THYRISTOR CA 1600V WC-500</p>	 <p>MCK500-12IO1 IXYS Corporation SCR THYRISTOR CA 1200V WC-500</p>	 <p>MCK700-12IO1W IXYS Corporation SCR THYRISTOR CA 1200V WC-500</p>
 <p>MCK500-18IO1 IXYS Corporation SCR THYRISTOR CA 1800V WC-500</p>	 <p>MCK501-16io1 IXYS IGBT Modules</p>	 <p>MCK501-14io1 IXYS IGBT Modules</p>	 <p>MCK501-18io1 IXYS IGBT Modules</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|--------------------|-----------------|--------------------|--------------------|
| 06031U220FAT2A | 2220PC105KAT1A | AD9949AKCPZ | ADM202EANZ | AP4024GEM |
| APT5012JVR | AT1463RE1U | BC81840MTF | BD3805F-E2. | CDRH6D26HPNP-1R5PC |
| CGA6P3X8R2A684M250AD | CL21C150JCANNNC | CL31B473MCCNNWC | CM600DZ-34H | DDTA143TUA-7-F |
| E72HA0.2B-A | EMC1053-2-ACZL-TR | FCX688BTA | FSV15100V | GRM1885C2A5R4CA01D |
| HD64180RP6 | IDT74CBTLV3245PGG8 | IRFR010TR | LB11963T-TLM-E | LE79Q2241VC |
| LM3880MFX-1AD | LP3470IM5-2.93 | LQH32MN330J23L | LT3080EMS8E-1#PBF | MAX7381AXR126 |
| MC34063AP | MC908JB8FBE | MCC255-08io1 | P042QH10 | PUSB3F4-TBR |
| R2J20702NP#G3G305 | R350SH10 | R9G04812XX | REG1117FA-1.8/KTTT | RT9164AGL |
| RT9166-15PVL | S07M-GS08 | SKKT213-12 | SKY65534-11 | SMAJ130CA-E3/61 |
| SUP45N03-13L-E3 | TCA0372DP1 | W9812G6JH-6P | WP-93154 24 | XC61FC4012PR |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited