


	<b>74HC283N,652</b>
	<b>Manufacturer Part Number:</b> 74HC283N,652
	<b>Manufacturer/Brand:</b> NXP Semiconductors / Freescale
	<b>Part of Description:</b> IC 4BIT BINARY FULL ADDER 16-DIP
<b>Datasheets:</b>	 <a href="#">74HC283N,652.pdf</a>
<b>RoHS Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

### Specifications

Part Number	74HC283N,652
Manufacturer	NXP Semiconductors / Freescale
Description	IC 4BIT BINARY FULL ADDER 16-DIP
Category	Integrated Circuits (ICs) > Logic - Specialty Logic
Part Status	Require For Quote & Check Stock
Series	74HC
Operating Temperature	-40°C ~ 125°C
Mounting Type	Through Hole
Package / Case	16-DIP (0.300", 7.62mm)
Supplier Device Package	16-DIP
Supply Voltage	2 V ~ 6 V
Number of Bits	4
Logic Type	Binary Full Adder with Fast Carry
Packaging	Tube

74HC283N,652 is New Original in Stock, Search 74HC283N,652 Datasheets, PDF, Inventory at Y-IC.com Online, Order 74HC283N,652 NXP Semiconductors / Freescale with warranted and confidence. RFQ 74HC283N,652 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>74HC283DB,118</b> NXP Semiconductors / Freescale IC 4BIT BINARY FULL ADDER 16SSOP</p>	 <p><b>74HC283DR SOP3.9</b> STM 74HC283DR SOP3.9 STM</p>	 <p><b>74HC283PW,118</b> NXP Semiconductors / Freescale IC 4BIT BINAR FULL ADDER 16TSSOP</p>	 <p><b>74HC299</b> ST 74HC299 ST</p>
 <p><b>74HC283DB</b> PHILIPS PHILIPS SSOP</p>	 <p><b>74HC283PW,112</b> NXP Semiconductors / Freescale IC 4BIT BINAR FULL ADDER 16TSSOP</p>	 <p><b>74HC298M</b> ST 74HC298M ST</p>	 <p><b>74HC283DB,112</b> NXP Semiconductors / Freescale IC 4BIT BINARY FULL ADDER 16SSOP</p>

### Hot Parts

More

- |                      |                    |                       |                      |                      |
|----------------------|--------------------|-----------------------|----------------------|----------------------|
| ⊛ 0603YC561JAT2A     | ↔ 08053D106KAT2A   | ⇒ 08055A181GAT2A      | D 1808HA390JAT9A     | ⇒ 1812CC683MAT1A     |
| ⊣ AD8054AR-REEL7     | ⊛ ADM3085JR        | D B330AF-13           | ⇒ BC847SE6327        | ⇒ BF423/BF422        |
| ⊛ BM80A-048L-033F50  | ⊣ BQ27542DRZR      | ⊛ C1005X5R1E334K050BB | ↔ CL21X106KPYNNE     | ⇒ CY8CTST242-LQI-01  |
| D DL4005-T           | ⊛ DTS2301A/DTS2301 | ⊣ DW025ABK-M          | ⊛ F6QP2G355R2SEMJ    | ⇒ FD800R33KF2-K      |
| ⇒ FM21LD16-60-TG     | ↔ FN4808C62        | ⊛ GAL16V8D-15LJ       | ⊣ GRM0336S1E1R6CD01D | ⇒ GRM1555C1E3R3B201D |
| ↔ ISL24813IRTZ       | ⇒ ISL6534CR        | D LM4051BEM3-1.2      | ⊛ MA22D2300LSO       | ⊣ MA2J7280GL+        |
| ⊛ MAX9516ALB+T       | D MAX9690CSA+T     | ⇒ MC74LCX86DTR2       | ↔ MOCD207R2M         | ⇒ MSP1018D           |
| ⊣ N2172ZD440         | ⊛ QM2417C1         | ↔ R7000203XXUA        | ⇒ S1703C-4.0960T     | ⇒ SI2307CDS-T1-E3    |
| ⊛ SLB9670VQ2.0FW7.61 | ⊣ SN75372P         | ⊛ TFM201610A-R40M-T00 | D TK60D08J1          | ⇒ TSV912IQ2T         |
| ↔ UCC27322QDRQ1      | ⊛ UCC2913DTRG4     | ⊣ V300C12C60AL        | ⊛ VI-26M-MU          | ⇒ WRF0503S-1W        |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited