



	<h2 style="color: red;">RX-8025SA:AC0</h2>	
	Manufacturer Part Number:	RX-8025SA:AC0
	Manufacturer/Brand:	Epson
	Part of Description:	IC RTC CLK/CALENDAR I2C 14-SOP
Datasheets:	 1.RX-8025SA:AC0.pdf	
	 2.RX-8025SA:AC0.pdf	
RoHs Status:	 Contains lead / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	









Specifications

Part Number	RX-8025SA:AC0
Manufacturer	Epson
Description	IC RTC CLK/CALENDAR I2C 14-SOP
Category	Integrated Circuits (ICs) > Clock/Timing - Real Time
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Clock/Calendar
Features	Alarm, Leap Year
Interface	I ² C, 2-Wire Serial
Package / Case	14-SOIC (0.197", 5.00mm Width)
Supplier Device Package	14-SOP
Voltage - Supply	1.7 V ~ 5.5 V
Memory Size	-
Time Format	HH:MM:SS (12/24 hr)
Date Format	YY-MM-DD-dd
Voltage - Supply, Battery	-
Current - Timekeeping (Max)	1.2µA ~ 1.8µA @ 3V ~ 5V
Packaging	Tape & Reel (TR)

RX-8025SA:AC0 is New Original in Stock, Search RX-8025SA:AC0 Datasheets, PDF, Inventory at Y-IC.com Online, Order RX-8025SA:AC0 Epson with warrantied and confidence. RFQ RX-8025SA:AC0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>RX-8025SA:AA3:PURE SN Epson IC RTC CLK/CALENDAR I2C 14-SOP</p>	 <p>RX-8025T EPSON RX-8025T EPSON</p>	 <p>RX-8025T UB EPSON RX-8025T UB EPSON</p>	 <p>RX-8025SA:AC3 PURE SN Epson IC TRC CLK/CALENDAR</p>
 <p>RX-8025T UC EPSON RX-8025T UC EPSON</p>	 <p>RX-8025SA:AC PURE SN Epson IC TRC CLK/CALENDAR</p>	 <p>RX-8025SAAC EPSON RX-8025SAAC EPSON</p>	 <p>RX-8025SA:AA3:ROHS Epson IC RTC CLK/CALENDAR I2C 14-SOP</p>

Hot Parts

[More](#)

- | | | | | |
|------------------------|---------------------------|----------------------|--------------------|-------------------------|
| ⊛ 08051A151GAT2A | ➔ 12065A200JAT4A | ➔ 955012661 | D ADM809TAKS-REEL7 | ➔ B38871-W1038-W310-A01 |
| ⊠ BCM20780B0KUBG | ⊛ BQ2000SN-B5 | D BY05-05S30L | ➔ CS3410B4 | ➔ CSTCR4M00G55-RO |
| ⊛ CY25561SXC-TBB | ⊠ CY62256LL-70ZRIT | ⊛ DS502ST12 | ➔ DTA143TKT | ➔ FA-050PY |
| D FXS41BM1-00-A0-LB0-L | ⊛ GRM21A5C2E271JW01D | ⊠ GRM32ER61A476KE20K | ⊛ ILC5061AM32X | ➔ IRF9520S |
| ➔ KIA78D06F-RTF/P | ➔ LCA110LSTR | ⊛ LP38853MR-ADJ | ⊠ LT3799IMSE#PBF | ➔ LTC1044ACS8#TRPBF |
| ➔ LTC3728IUH#TRPBF | ➔ MB89191APF-G-587-ER-RE1 | D MC68HC908QB8E0MDTE | ⊛ MIC2009BM6 | ⊠ MJD210TM |
| ⊛ MK22FN1M0VLL12 | D MMF300S060DA | ➔ NTCG204AH473JT1 | ➔ PCF7935AS | ➔ PS8558BTQFN24GTR2-A0 |
| ⊠ RB051M-2YTR | ⊛ S29AL004D70TFI02 | ➔ SFH6186-3T | ➔ SI-8005Q | ➔ SKR130/18 |
| ⊛ SMP1302-011LF | ⊠ SN74CB3T3125PWR | ⊛ SN74CBT3383CDBQR | D SP213EEA | ➔ SP3072EMN |
| ➔ SW36CXC920 | ⊛ TDA1515AQ | ⊠ TMP47C241M-J837 | ⊛ TPCP8202 | ➔ TZMB16-GS08 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited