










	<b>ISL88001IH22Z-T7A</b>
	<b>Manufacturer Part Number:</b> <a href="#">ISL88001IH22Z-T7A</a>
	<b>Manufacturer/Brand:</b> Intersil
	<b>Part of Description:</b> IC VOLT SUPERVISOR 2.19V SOT23-3
<b>Datasheets:</b>  <a href="#">ISL88001IH22Z-T7A.pdf</a>	<b>RoHS Status:</b>  Lead free / RoHS
<b>Stock Condition:</b> Compliant New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	<a href="#">ISL88001IH22Z-T7A</a>
Manufacturer	Intersil
Description	IC VOLT SUPERVISOR 2.19V SOT23-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	TO-236-3, SC-59, SOT-23-3
Supplier Device Package	SOT-23-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.19V
Packaging	Original-Reel®

ISL88001IH22Z-T7A is New Original in Stock, Search ISL88001IH22Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88001IH22Z-T7A Intersil with warrantied and confidence. RFQ ISL88001IH22Z-T7A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<b>In:</b>    <b>ISL88001IH22Z-T</b> Intersil IC VOLT SUPERVISOR 2.19V SOT23-3	  <b>ISL88001IH23Z-T7A</b> Intersil IC VOLT SUPERVISOR 2.32V SOT23-3	  <b>ISL88001IH17Z-T</b> Intersil IC VOLT SUPERVISOR 1.67V SOT23-3	  <b>ISL88001IH17Z-T7A</b> Intersil IC VOLT SUPERVISOR 1.67V SOT23-3
  <b>ISL88001IH23Z-TK</b> Intersil IC VOLT SUPERVISOR 2.32V SOT23-3	  <b>ISL88001IH16Z-TK</b> Intersil IC VOLT SUPERVISOR 1.58V SOT23-3	  <b>ISL88001IH22Z-TK</b> Intersil IC VOLT SUPERVISOR 2.19V SOT23-3	  <b>ISL88001IH26Z-T</b> Intersil IC VOLT SUPERVISOR 2.63V SOT23-3

### Hot Parts

[More](#)

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited