


	<p>S-1009C41I-N4T1U</p>
	<p>Manufacturer Part Number: S-1009C41I-N4T1U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR</p>
	<p>Datasheets:  S-1009C41I-N4T1U.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-1009C41I-N4T1U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-1009
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.1V
Packaging	Tape & Reel (TR)

S-1009C41I-N4T1U is New Original in Stock, Search S-1009C41I-N4T1U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-1009C41I-N4T1U SII Semiconductor Corporation with warrantied and confidence. RFQ S-1009C41I-N4T1U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-1009C42I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C40I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C42I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C41I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>
 <p>S-1009C41I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C43I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C43I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C42I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>

Hot Parts

More

- | | | | | |
|--|--|---|---|---|
|  1DI50A-060 |  2225AC683KAT1A\SB |  AAT3692IRN-4.2-T1 |  AD8055ARTZ |  AUR9801DGDR |
|  BA15218F-DXE2 |  BFP405FE6327 |  C0603X5R1H221K |  CR3100SB |  CSFMT101-HF |
|  DAC7731E/1KG4 |  DF600R12IP4D |  EC4409C-TL-H |  EMI8142MUTAG |  EMK325BJ226MMHT |
|  FDD20AN06_F085 |  FM24C256A |  FSV12120V |  GRM152R60J105ME15D |  ILQ55-X009 |
|  IRFBC30S |  KC5032A30.0000CMOE00 |  LM385BLP-1-2 |  LP3881ESX-1.5 |  LTC1682CMS8#TRPBF |
|  M24C08-MN6T |  M25PE40-VMW |  MAX5949BESA |  MCR50JZHJ334 |  MIC5205-3.3BM5TR |
|  MPC850DEZQ50BU |  MPM7128QC100AA |  MQG100H100 |  NJM2700L |  NL322522T-R22K-3-PF |
|  PI5C33X257BEX |  PQ1U331M2ZPH |  PT4450-LF |  RD28F6408W30BH |  RLS4148 TE-11 |
|  S-1000C38-I4T1G |  S-8357N33MC-02ST2G |  SFW30R-3STAE1LF |  SI4833ADY-T1-E3 |  SY88933ALEYTR |
|  TCM811SERC |  TV15C120JB-G |  TW8816-DELA3-GR |  VI-JNR-CX |  VI-JT4-CX |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited