

	<h2 style="color: red;">74LS595N</h2>
	<p>Manufacturer Part Number: 74LS595N</p> <p>Manufacturer/Brand: TI</p> <p>Part of Description: TI DIP16</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 8500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	74LS595N
Manufacturer	TI
Description	TI DIP16
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	8500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

74LS595N is New Original in Stock, Search 74LS595N Datasheets, PDF, Inventory at Y-IC.com Online, Order 74LS595N with warrantied and confidence. RFQ 74LS595N : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>74LS642N TI TI DIP</p>	 <p>74LS597N TI TI DIP16</p>	 <p>74LS573AN TI TI DIP</p>	 <p>74LS641N TI TI DIP20</p>
 <p>74LS640N TI TI DIP</p>	 <p>74LS564PC F F DIP-20P</p>	 <p>74LS640 TI TI SOP20 7</p>	 <p>74LS54N SIG/MOT 74LS54N SIG/MOT</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|-----------------------|--------------------------|-----------------------|--------------------------|
| ⚙️ 04023A0R3BAT2A | ➡️ 08051C104K4T2A | ➡️ 1367645-4 | D 1812HA270JAT1A | ➡️ 2N7002 T/R |
| ⊖ ACM2012E-121-2P-T00 | ⚙️ AD7011ARS-REEL | D ADD8710ARUZ | ➡️ B1512S-W75 | ➡️ B39182-B9402-K610-S05 |
| ⚙️ BCM2048KUBG-PII | ⊖ BD6236FM | ⚙️ BZD27C20P-M-08 | ➡️ BZX84-C9V1/B | ➡️ C1608Y5V1A105Z/10 |
| D C3216X7S1A156M160AC | ⚙️ CC0201CRNP09BN2R7 | ⊖ CF3450H2 | ⚙️ CS5506-BS | ➡️ CVKA100LS12-05-S |
| ➡️ CY2308SXI-1HT | ➡️ DM7406MX | ⚙️ DSPIC33FJ64MC804-I/PT | ⊖ ESD5302F | ➡️ GM66015-3.3TA3R |
| ➡️ HCNR201#500 | ➡️ LP3985IM5-3.3/NOPB | D LTC1154CS8#PBF | ⚙️ LTC3545EUD#TRPBF | ⊖ M4LV-96/48-15VNC |
| ⚙️ MAX9725CEBC+TG47 | D MBRB41H100CG | ➡️ MC-10149F1-CB2-E2-A | ➡️ MC35XS3500HFK | ➡️ NJU7700F29 |
| ⊖ P0250.474T | ⚙️ PCF8579H/1 | ➡️ S3JHE3/57T | ➡️ SFH229PFA | ➡️ SFH6106-3X007T |
| ⚙️ SKMD100/18E | ⊖ SM16CXC220 | ⚙️ SP6260EEK-L | D ST3215SB32768OMRONH | ➡️ T548N19TOF |
| ➡️ TC74VHC10FT | ⚙️ TPA6211A1DRB | ⊖ TPS380G30DBVR | ⚙️ UCC29002DR/1 | ➡️ VI-24L-IX |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited