
 <p>A Renesas Company</p>	<p>ISL6244HR</p>
	<p>Manufacturer Part Number: ISL6244HR</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC REG CTRLR BUCK 32QFN</p> <p>Datasheets:  ISL6244HR.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	ISL6244HR
Manufacturer	Intersil
Description	IC REG CTRLR BUCK 32QFN
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-10°C ~ 100°C (TA)
Output Type	PWM Signal
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Function	Step-Down
Frequency - Switching	80kHz ~ 1MHz
Number of Outputs	4
Output Configuration	Positive
Voltage - Supply (Vcc/Vdd)	4.75 V ~ 5.25 V
Topology	Buck
Control Features	Enable, Frequency Control, Power Good
Output Phases	4
Duty Cycle (Max)	75%
Synchronous Rectifier	-
Clock Sync	No
Serial Interfaces	-
Packaging	Tube

ISL6244HR is New Original in Stock, Search ISL6244HR Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6244HR Intersil with warrantied and confidence. RFQ ISL6244HR : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>ISL6244CRZ Intersil IC REG CTRLR BUCK 32QFN</p>	 <p>ISL6244HRZ Intersil IC REG CTRLR BUCK 32QFN</p>	 <p>ISL6247CR-T Intersil IC REG CTRLR 40QFN</p>	 <p>ISL6244HR-T Intersil IC REG CTRLR BUCK 32QFN</p>
 <p>ISL6244CR-T Intersil IC REG CTRLR BUCK 32QFN</p>	 <p>ISL6244HRZ-T Intersil IC REG CTRLR BUCK 32QFN</p>	 <p>ISL6247CR Intersil IC REG CTRLR 40QFN</p>	 <p>ISL6244CR Intersil IC REG CTRLR BUCK 32QFN</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|---------------------|--------------------------|--------------------|
| ⊛ 1210SC181KAT1A | ↔ 1812AA221JAT3A | ⇒ AIC1647CV | D AP431AWG | ⇒ APX810-44SRG-7 |
| ⊣ BCR5AS-12B | ⊛ BSR316PH6327 | D BZX84-C2V7 | ⇒ CGA6M2X7R1H155K200AD | ⇒ CL03C0R3BA3GNNH |
| ⊛ CL03C3R6BA3GNNH | ⊣ EZ1117CM-3.3TRT | ⊛ FAN5776UCX | ↔ FSLM2520-R10J/2520-R10 | ⇒ GWS4805S3 |
| D HSMS-2824-BLKG | ⊛ HT66F018 | ⊣ IRS2052TRPBF | ⊛ KSD2012GTU | ⇒ LC75372EHS |
| ⇒ LPC1XXXFBD64 | ↔ LQP03TN3N6B02D | ⊛ MEA2010LC040T002 | ⊣ MGB15N40CL | ⇒ MIC5247-1.8BM5 |
| ↔ MP321P3XC | ⇒ MSM5117805D-60JSR1 | D PSS15S92F6-AG | ⊛ RLZTE-117.5B-7V5 | ⊣ RT9169-16CX |
| ⊛ S-80828CLNB-B6NT2G | D SBL3071M | ⇒ SI7922DN-T1-E3 | ↔ SKiiP25NAB066V10 | ⇒ SMAJ120CA-E3/61 |
| ⊣ SMM310E6433 | ⊛ SP3243BCA | ↔ SQM110N06-04L-GE3 | ⇒ STTH5L06B | ⇒ T55T476M6R3C0070 |
| ⊛ TD75N1200KOF | ⊣ TPS84210RKGR | ⊛ TZX5V6B-TAP | D UMK105BJ222MV-F | ⇒ VI-20L-MX |
| ↔ VI-26R-CY | ⊛ VI-B6Y-EU | ⊣ VLS6045EX-2R0N | ⊛ VT223CR-ADJ | ⇒ WRF0505S-W5 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited