


	<p>S-80854CNY-B2-U</p>
	<p>Manufacturer Part Number: S-80854CNY-B2-U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 5.4V TO-92</p>
	<p>Datasheets:  S-80854CNY-B2-U.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	S-80854CNY-B2-U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 5.4V TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Voltage Detector
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	5.4V
Packaging	Bulk

S-80854CNY-B2-U is New Original in Stock, Search S-80854CNY-B2-U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80854CNY-B2-U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80854CNY-B2-U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80854CNUA-B9FT2G SII Semiconductor Corporation IC VOLT DETECTOR 5.4V SOT89-3</p>	 <p>S-80854CNPF-B9FTFG SII Semiconductor Corporation IC VOLT DETECTOR 5.4V SNT-4A</p>	 <p>S-80854CNY-B-G SII Semiconductor Corporation IC VOLT DETECTOR 5.4V TO-92</p>	 <p>S-80855CLMC-B7GT2G SII Semiconductor Corporation IC VOLT DETECTOR 5.5V SOT23-5</p>
 <p>S-80855CLMC-B7GT2U SII Semiconductor Corporation IC VOLT DETECTOR 5.5V SOT23-5</p>	 <p>S-80854CNPF-B9FTFU SII Semiconductor Corporation IC VOLT DETECTOR 5.4V SNT-4A</p>	 <p>S-80854CNY-Z2-U SII Semiconductor Corporation IC VOLT DETECTOR 5.4V TO-92</p>	 <p>S-80855ANNP SEIKO S-80855ANNP SEIKO</p>

Hot Parts

More

- | | | | | |
|--------------------|------------------|---------------------|--------------------|-------------------|
| 0805ZC474MAT2A | 12063A472GAT4A | 12065A111FAT2A | D 12103C105KAZ2A | 1808CC153MAT1A |
| 18121C184KAT2A | 5050661610 | AD7414ARM-0REEL7 | ADS1211E/1K | AP1682UMTR-G1 |
| AP8800AWT-7 | BTNA14N3 | BZG03C27TR3 | C3216CH2J102J085AA | CC1210KKX5R8BB475 |
| D CGA4F3X7R2E152K | CL10C040CB8NNNC | CLC409AJM5X | DTC124XMT2L | EDJ1116EJBG-GN-F |
| FAN5355BUC05X | FDPF5N50NZ | FQB11P06TM**CN-SCI | FQD2N60TM | GA100HS120K |
| GRM2197U2A8R2DD01D | LFB32871MSA1A595 | LMX2531LQ1146E/NOPB | MAX3768CUA+T | MAX5003EEE-TG |
| MAX809TEUR+ | MK1491E-14R | MMDFS3P303R2 | MTT40A16N | N105PH16 |
| NCP2811BMTTXG | NRC06F2003TR | S29AL016M90BAI010 | SIA813DJ-T1-GE3 | SM6A10NSU |
| SMDA05-LF | SP490EEP-L | SQCSVA0R4BAT1A | D SZP6SMB11CAT3G | T298N06TOC |
| TOTX179U | TT500N16KOF TIM | VBO72-18N07 | WM8976CGEFL | XC9536-15PCG44C |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited