


	<p><b>S-80913CLPF-G6HTFU</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">S-80913CLPF-G6HTFU</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">SII Semiconductor Corporation</a></p> <p><b>Part of Description:</b> IC VOLT DETECTOR 1.3V SNT-4A</p> <p><b>Datasheets:</b>  <a href="#">S-80913CLPF-G6HTFU.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	


### Specifications

Part Number	S-80913CLPF-G6HTFU
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.3V SNT-4A
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	4-SMD, Flat Leads
Supplier Device Package	SNT-4A
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	2.7 ms Minimum
Voltage - Threshold	1.3V
Packaging	Tape & Reel (TR)

S-80913CLPF-G6HTFU is New Original in Stock, Search S-80913CLPF-G6HTFU Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80913CLPF-G6HTFU SII Semiconductor Corporation with warrantied and confidence. RFQ S-80913CLPF-G6HTFU : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>S-80913CLMC-G6HT2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p><b>S-80913CNMC-G8HT2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p><b>S-80913CNNB-G8HT2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SC-82AB</p>	 <p><b>S-80913CLNB-G6HT2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SC-82AB</p>
 <p><b>S-80913CNNB-G8HT2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SC-82AB</p>	 <p><b>S-80913CNMC</b> SEIKO S-80913CNMC SEIKO</p>	 <p><b>S-80913CLMC-G6HT2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p><b>S-80913CLPF-G6HTFG</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SNT-4A</p>

### Hot Parts

More

- |                       |                     |                        |                        |                      |
|-----------------------|---------------------|------------------------|------------------------|----------------------|
| ⊛ 04023A201KAT2A      | ↔ 06031C301KAT2A    | ⇒ 08052U6R2DAT2A       | D 1808SC222MAT1A       | ⇒ AD8307AR           |
| ⊣ AD9057BRS-RL60      | ⊛ AD9238BSTZ-20     | D AD9967BCPZRL         | ⇒ ADS7957SRHBR         | ⇒ AMS1085CT-2.5      |
| ⊛ C3216X5R1A106K160AB | ⊣ CC0402KRX5R9BB102 | ⊛ CGA3E2X8R1H682M080AA | ↔ CY62256NLL-70SNXI    | ⇒ FS6R06VL4-B2       |
| D HD6473724H          | ⊛ HHM1775C1         | ⊣ HSL226KRF            | ⊛ ICS83054AGI-01LF     | ⇒ ID126030           |
| ⇒ IDT06S60C           | ↔ IP4791CZ12        | ⊛ IRM-H600JW           | ⊣ LM4041BELT-1.2       | ⇒ LT1352CS8          |
| ↔ MBR5240LT3          | ⇒ PDR5K-13          | D PM-10AD14            | ⊛ RJK6032DPH-E0        | ⊣ S-80845CNNB-B86-T2 |
| ⊛ S29GL512N11FFA02    | D SBF-5089Z         | ⇒ SC4216STRT           | ↔ SESD5Z5VGP           | ⇒ SMAJ40CA-TR        |
| ⊣ T9G0141603DH        | ⊛ TCM2010-261-4P-T  | ↔ TISP4C015L1NR-S      | ⇒ TK11234BMCL          | ⇒ TOP266VG           |
| ⊛ TSS8J48SR           | ⊣ V110A48C400BL3    | ⊛ VCA2617RHBR          | D VHO55-08             | ⇒ VI-241-IV          |
| ↔ VI-J64-CY-S         | ⊛ WSL40261L000FEA   | ⊣ XC6118C32AMR-G       | ⊛ XPGWHT-01-0000-00FE6 | ⇒ ZXMD65P02N8TC      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited