

 <p>A Renesas Company</p>	<p>X5329V14</p>
	<p>Manufacturer Part Number: X5329V14</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p>Datasheets:  X5329V14.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, 1400 pcs Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	X5329V14
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	1400 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-SOIC (0.154", 3.90mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tube

X5329V14 is New Original in Stock, Search X5329V14 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5329V14 Intersil with warrantied and confidence. RFQ X5329V14 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5329V14I Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5329S8ZT1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5329S8Z-2.7A Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5329V XICOR XICOR TSSOP14</p>
 <p>X5329V14-2.7T1 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5329V14-4.5A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5329S8Z-4.5A Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5329V14-2.7 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>

Hot Parts

More

- | | | | | |
|---|---|--|--|---|
| <ul style="list-style-type: none"> ⊕ 1206YC274KAT2A ⊖ A50L-0001-0332 ⊕ CQ0402JRNPO9BN270 D GRM21B7U2A911JZ01L ⇒ ISL9003AIEHZ-T ⇒ MA8027-H ⊕ MMBF5484 ⊖ OPA347NA/250G4 ⊕ SMBJ130A-TR ⇒ TLV1701AIDBVR | <ul style="list-style-type: none"> ⇒ 1812CA221KATRE ⊕ AON7404G ⊖ E0400YH240 ⊕ GRM21BR72D223KW03L ⇒ KD70F-40 ⇒ MAX1720EUT+T D MMSZ5234B-TG ⊕ QM75TX-H2 ⊖ SMBZ5942B ⊕ TLV71315PDQNR | <ul style="list-style-type: none"> ⇒ 1812SC172KAT1A D BSM50GAL100D ⊕ EE87C196MC ⊖ H11L2.300W ⊕ LC4032V-75TN48I D MAX1771CPA ⇒ MX25U3235FZCI-10G ⇒ RT9169-12CX ⊕ SN105225DBTR ⊖ TMK063CG270JT-F | <ul style="list-style-type: none"> D 2MBI200U4B120-50 ⇒ BZM55B4V3-TR ⇒ ESAG31-060T ⊕ IDT2308-1HPG ⊖ LM2903PWR ⊕ MC10E131FNR2 ⇒ NJM072BD ⇒ S-1131B30UA-N4P D T1051N24TOF ⊕ UCC3802DTR | <ul style="list-style-type: none"> ⇒ 6DI15S-040C-01 ⇒ CDBMH160-G ⇒ GP300LSS16S-7079 ⇒ IRGS15B60KDTRRPBF ⇒ LM87CIMT ⊖ MCR8DSMT4G ⇒ NP180N04TUG ⇒ SI4446DY-T1-E3 ⇒ TA550CPF8 ⇒ W25Q32BVSTIM |
|---|---|--|--|---|

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited