










	<h2 style="color: red;">LB1909MC-BH</h2>
	<b>Manufacturer Part Number:</b> LB1909MC-BH
	<b>Manufacturer/Brand:</b> AMI Semiconductor / ON Semiconductor
	<b>Part of Description:</b> IC MOTOR DRIVER PAR 10SOIC
	<b>Datasheets:</b>  <a href="#">LB1909MC-BH.pdf</a>
	<b>RoHS Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, 1800 pcs Stock Available.
<b>Ship From:</b> Hong Kong	
<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS	

### Specifications

Part Number	LB1909MC-BH
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER PAR 10SOIC
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	1800 pcs Stock
Series	-
Technology	Bipolar
Operating Temperature	-30°C ~ 85°C (TA)
Mounting Type	Surface Mount
Interface	Parallel
Applications	General Purpose
Package / Case	10-SOP (0.154", 3.90mm Width)
Supplier Device Package	10-SOIC
Voltage - Supply	2.5 V ~ 16 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	-
Output Configuration	Half Bridge (4)
Voltage - Load	2.5 V ~ 16 V
Motor Type - Stepper	Bipolar
Motor Type - AC, DC	-
Step Resolution	-
Packaging	Tape & Reel (TR)

LB1909MC-BH is New Original in Stock, Search LB1909MC-BH Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1909MC-BH AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1909MC-BH : Info@Y-IC.com

### You May Be Also Be interested

 <b>LB1910</b> SANYO SANYO SOP28	 <b>LB1897H-TE-L</b> SANYO SANYO HSOP28.	 <b>LB1906CL-TLM</b> SANYO LB1906CL-TLM SANYO	 <b>LB1920-E</b> AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER 3PH 28SDIP
 <b>LB1909MCGEV</b> AMI Semiconductor / ON Semiconductor BOARD EVAL FOR LB1909MC	 <b>LB1920-N-E</b> AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER 3PH 28SDIP	 <b>LB1916</b> SANYO SANYO QFP	 <b>LB1909M-TE-L-E</b> AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR MFP10S

### Hot Parts More

- |                    |                       |                     |                     |                     |
|--------------------|-----------------------|---------------------|---------------------|---------------------|
| ⊕ 0402YA470JAT4A   | ↔ 06033C123KAT4A      | ⇒ 12103G334ZAT2A    | D 1SMC36AT3         | ⇒ 6MBP50UA-060      |
| ⊖ AD7938BCPZ       | ⊕ C2012X5R0J225M/1.25 | D CE62H256AK-15     | ⇒ CM75DY-28K        | ⇒ CS5233-3GDF8      |
| ⊕ CY8C21312-12PVXE | ⊖ EDZVT2R4.7B         | ⊕ ESD63C225K4T2A-30 | ↔ F0900VF450        | ⇒ GN2012-TX         |
| D IRS2011STRPBF.   | ⊕ LFB182G45CGFD436    | ⊖ LIS244ALHTR       | ⊕ LM2940IMP-12/NOPB | ⇒ LMV774MT/NOPB     |
| ⇒ LT1962EMS8-1.8   | ↔ LT1991ACMS          | ⊕ LTC4261CGN        | ⊖ M02094G-12        | ⇒ MA2Z72000         |
| ↔ MAX489EESD       | ⇒ MAX680CSA           | D MCT5200.S         | ⊕ MIC2584-JYTS      | ⊖ MIC5365-3.3YMT-TZ |
| ⊕ MM3124FPRE       | D MT9160AE            | ⇒ N560DH36LOO       | ↔ RCV5933AN-F       | ⇒ S-1721A1218-I6T1G |
| ⊖ SFH1690-BX001T   | ⊕ SI7540DP-T1-E3      | ↔ SN74AUC1G07DCKRG4 | ⇒ STK621-140A       | ⇒ STM1001SBWX6F     |
| ⊕ TC7USB221WBG1    | ⊖ THS4140CDGNR        | ⊕ TLV2362IDGK       | D TS7912CZ          | ⇒ UPD78F0532AGB     |
| ↔ VE-221-EW        | ⊕ VS-6CWQ04FNTRL-M3   | ⊖ VUO28-08N07       | ⊕ XC6221A3127R-G    | ⇒ YPPD-J016E        |