










 A Renesas Company	ISL59421IU-T7
	Manufacturer Part Number: ISL59421IU-T7
	Manufacturer/Brand: Intersil
	Part of Description: IC AMP MULTIPLEX 865MHZ 10-MSOP
	Datasheets:  ISL59421IU-T7.pdf
	RoHs Status: Contains lead / RoHS non-compliant
Stock Condition: New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	ISL59421IU-T7
Manufacturer	Intersil
Description	IC AMP MULTIPLEX 865MHZ 10-MSOP
Category	Integrated Circuits (ICs) > Linear - Amplifiers - Video
Part Status	Require For Quote & Check Stock
Series	-
Current - Supply	14.5mA
Mounting Type	Surface Mount
Output Type	-
Applications	2:1 Multiplexer-Amplifier
Package / Case	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Supplier Device Package	10-MSOP
Number of Circuits	1
Current - Output / Channel	180mA
Slew Rate	2008 V/μs
-3db Bandwidth	865MHz
Voltage - Supply, Single/Dual (±)	-
Packaging	Tape & Reel (TR)

ISL59421IU-T7 is New Original in Stock, Search ISL59421IU-T7 Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL59421IU-T7 Intersil with warrantied and confidence. RFQ
ISL59421IU-T7 : Info@Y-IC.com

You May Be Also Be interested

In:  ISL59424IR-T13 Intersil IC AMP TRIPLE MUX 1GHZ 24-QFN	 ISL59424IRZ intersil intersil QFN24	 ISL59420IUZ-T13 Intersil IC AMP MULTIPLEX 400MHZ 10-MSOP	 ISL59421IUZ Intersil IC AMP MULTIPLEX 865MHZ 10-MSOP
 ISL59424IR-T7 Intersil IC AMP TRIPLE MUX 1GHZ 24-QFN	 ISL59420IUZ-T7 Intersil IC AMP MULTIPLEX 400MHZ 10-MSOP	 ISL59421IU Intersil IC AMP MULTIPLEX 865MHZ 10-MSOP	 ISL59421IU-T13 Intersil IC AMP MULTIPLEX 865MHZ 10-MSOP

Hot Parts

[More](#)

- | | | | | |
|---|---|--|---|---|
|  0201YC331JAT2A |  AD9200JST |  ADC122S101CIMMX |  ADG201AKR-REEL7 |  ADM825LYKSZ/ADM825SYKSZ |
|  AP1522WA |  AT403S05 |  B2100-HF |  BD45452G-TR |  BZX84B12-7-F |
|  C0402C0G1C430J |  CC0603KRX5R9BB104 |  CGJ3E2C0G2A102J080AA |  CL05A435MR5NWC |  CU0131220JAT2A |
|  D CY7C1305TV25-167BZC |  DCX144EU-7 |  DD46S08K-K |  DG9451EN-T1-E4 |  DSA405-44A |
|  EXQ125-48S2V5-ZRJ |  FAN7380MX |  FQPF30N06 |  GRM2165C2A222JA01J |  GRM32DR61C10KA01L |
|  HEDS-9140#G00 |  IMP706PESA |  IRFK3F250 |  LMP8601QMAX |  LT1491AIS#PBF |
|  M5M5278DVP-20L |  MC13892VL |  NT5CB256M16BP-DI |  P06P03LCGA |  S-80832CNPF-B8RTFG |
|  SAYRF1G73CA0F0AR15 |  SFR300L6P1 |  SI1865DDL-T1-GE3 |  SMCJ22CA-E3/57 |  SN1110021PWPR |
|  SN74F32D |  SN74LVTH16244ADLR |  SPX2954M3-L-3.3/TR |  STB14NK60ZT4 |  TPL0102-100PWR |
|  TPS54352PWPRG4 |  V48C3V3H75BL |  VI-2NV-CV |  VI-J61-10 |  W1856NC420 |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited