

	<p>Manufacturer Part Number: MB85RQ4MLPF-G-BCERE1</p>
	<p>Manufacturer/Brand: Fujitsu Electronics America, Inc.</p>
	<p>Part of Description: IC FRAM 4MBIT 108MHZ 16SOP</p>
	<p>Datasheets:  MB85RQ4MLPF-G-BCERE1.pdf</p>
<p>RoHs Status:</p>	<p>Stock Condition: New original, Stock Available.</p>
<p>Ship From:</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	


Specifications

Part Number	MB85RQ4MLPF-G-BCERE1
Manufacturer	Fujitsu Electronics America, Inc.
Description	IC FRAM 4MBIT 108MHZ 16SOP
Category	Integrated Circuits (ICs) > Memory
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Interface	SPI, QSPI
Package / Case	16-SOIC (0.295", 7.50mm Width)
Supplier Device Package	16-SOP
Voltage - Supply	1.7 V ~ 1.95 V
Memory Type	Non-Volatile
Speed	108MHz
Memory Size	4Mb (512K x 8)
Memory Format	FRAM
Packaging	Tape & Reel (TR)

MB85RQ4MLPF-G-BCERE1 is New Original in Stock, Search MB85RQ4MLPF-G-BCERE1 Datasheets, PDF, Inventory at Y-IC.com Online, Order MB85RQ4MLPF-G-BCERE1 Fujitsu Electronics America, Inc. with warrantied and confidence. RFQ MB85RQ4MLPF-G-BCERE1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MB85RC64VPNF-G-TNERE1 FUJITSU MB85RC64VPNF-G-TNERE1 FUJITSU</p>	 <p>MB85RS128BPNF-G-JNERE FUJITSU MB85RS128BPNF-G-JNERE FUJITSU</p>	 <p>MB85RC64VPNF-G-JNE1 FUJITSU FUJITSU SOP8</p>	 <p>MB85RS128APNF-G-JNE1 Fujitsu Electronics America, Inc. IC FRAM 128KBIT 25MHZ 8SOP</p>
 <p>MB85RS128BPNF-G-JNE1 Fujitsu Electronics America, Inc. IC FRAM 128KBIT 25MHZ 8SOP</p>	 <p>MB85RS128BPNF-G-JNERE1 Fujitsu Electronics America, Inc. IC FRAM 128KBIT 33MHZ 8SOP</p>	 <p>MB85RS128APNF-G-JNERE1 FUJITSU MB85RS128APNF-G-JNERE1 FUJITSU</p>	 <p>MB85RC64VPNF-G-JNERE FUJITSU MB85RC64VPNF-G-JNERE FUJITSU</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|------------------|----------------------|----------------------|
| ⊛ 04025A4R7CAJ2A | ↔ 06035A2R2JAT2A | ⇒ 18125A472JAT2A | D ADG609BR-REEL | ⇒ ADSP-BF533SKBCE10D |
| ⊣ AIC1680-N26CUTR | ⊛ AM29843PC | D AS7815AT-E1 | ⇒ AUIRFR4615TRPBF | ⇒ AXK5F34345J |
| ⊛ B130LB-13 | ⊣ BCM5351GKPBG | ⊛ BXB100-48S05-H | ↔ BZB84-B12 | ⇒ C2225C225J5RAC7800 |
| D CDBMHT150-HF | ⊛ DBA200UA60 | ⊣ DDTC144EE-7-F | ⊛ GRM0225C1E101JA02L | ⇒ GRM0335C1H3R3BA01D |
| ⇒ GRM0337U1E360GD01D | ↔ GRM1556T1H6R8DD01D | ⊛ HAT1097RJ-EL-E | ⊣ IRF7603TRPBF | ⇒ IRKL330-08 |
| ↔ KA75420ZTA | ⇒ KT224510 | D L-07C2N7SV6T | ⊛ LMV824Q1MTX/NOPB | ⊣ M508014F |
| ⊛ MAX4491AUA+T | D MC74VHC1G02DFT2 | ⇒ MTZJT-7710C | ↔ NFC20-48S12-4 | ⇒ NJM7805DL1A |
| ⊣ PH100S48-12N/NTL | ⊛ PIC16F687-I/ML | ↔ QRD2412001 | ⇒ S-1170B51UC-OUKTFG | ⇒ SSC-225HV |
| ⊛ SP30S-4805 | ⊣ SV48-26-240 | ⊛ SVD10N65F | D TAJA476M004RNJ | ⇒ TMP275AIDGKT |
| ↔ TSX631AILT | ⊛ TT32N1600KOC | ⊣ VI-20Y-CX | ⊛ VLF3012AT-2R2M1R0 | ⇒ YW1015A |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited