










	B59701A90A62
	Manufacturer Part Number: B59701A90A62
	Manufacturer/Brand: EPCOS
	Part of Description: B59701A90A62 EPCOS (TDK)
Datasheets:  B59701A90A62.pdf	
RoHs Status:  Lead free / RoHS Compliant	
Stock Condition: New original, 32000 pcs Stock Available.	
Ship From: Hong Kong	
Shipment Way: DHL/Fedex/TNT/UPS/EMS	

Specifications

Part Number	B59701A90A62
Manufacturer	EPCOS
Description	B59701A90A62 EPCOS (TDK)
Category	Sensors, Transducers > Temperature Sensors - PTC
Part Status	32000 pcs Stock
Series	B59701
Operating Temperature	-
Mounting Type	Non-Standard, Leadless
Power - Max	-
Package / Case	0805 (2012 Metric)
Supplier Device Package	0805
Resistance Tolerance	-
Resistance in Ohms @ 25°C	1k
Packaging	Tape & Reel (TR)

B59701A90A62 is New Original in Stock, Search B59701A90A62 Datasheets, PDF, Inventory at Y-IC.com Online, Order B59701A90A62 EPCOS with warranted and confidence. RFQ B59701A90A62 : Info@Y-IC.com

You May Be Also Be interested In:

 <p>B59701A70A62 EPCOS THERMISTOR PTC1KOHM 70 DEG 0805</p>	 <p>B59701A140A62 EPCOS PTC THERMISTOR A 701A 70A 62</p>	 <p>B59703 infineon B59703 infineon</p>	 <p>B59701A130A62 EPCOS THERMISTOR PTC 1KOHM 130DEG 0805</p>
 <p>B59702 International Rectifier (Infineon Technologies) B59702 infineon</p>	 <p>B59707A0120A062 EPCOS PTC RESET FUSE 80V 50MA 1210</p>	 <p>B59701A120A62 EPCOS THERMISTOR PTC 1KOHM 120DEG 0805</p>	 <p>B59702AB Infineon Infineon MQFP80</p>

Hot Parts

More

- | | | | | |
|-------------------------|----------------------|-----------------------|---------------------|-----------------------|
| ⚙️ 12061A392KAT2A | ➡️ 12061A471FAT7A | ➡️ 12061C153KAT4A | D 7MBR75SB060-01 | ➡️ AH175-PL-B-B |
| ⚡ AP4500GM | ⚙️ AT90CAN64-15AT | D B59008C110A40 | ➡️ B59100C130A70Z15 | ➡️ B59115P1120A62 |
| ⚙️ B59535T1120A262 | ⚡ B59550T1120A262 | ⚙️ B59602A0055B062 | ➡️ B59602A0055B062 | ➡️ B59701A110A62V1 |
| D B59707A0120A062 | ⚙️ B59707A0120A062 | ⚡ B59721A110A62 | ⚙️ B59750B120A70 | ➡️ B59774B115A70Z15 |
| ➡️ B59835T1120A62 | ➡️ B59901D100A40 | ⚙️ B59945C160A70 | ⚡ B59980C0120A051 | ➡️ B59980C0120A051 |
| ➡️ B59980C120A51Z15 | ➡️ B59985-C120-A70 | D B59990C0080A051 | ⚙️ B59990C0080A051 | ⚡ BZX84C4V3-7 |
| ⚙️ CGA3E2C0G1H103J080AA | D DS1021S-25 | ➡️ FDT439N-NL | ➡️ FODM3062R1 | ➡️ GRM21BR60J335KA11K |
| ⚡ KC7050P125.000P30E00 | ⚙️ LT1513CR | ➡️ MBM29DL64DF-70PFTN | ➡️ PSND50E/04 | ➡️ R600CH21 |
| ⚙️ SI7862ADP-T1-GE3 | ⚡ SPP08P06PH | ⚙️ STR55041 | D TDA5247HT | ➡️ TLC3574IN |
| ➡️ TMK107B7223KAHT | ⚙️ TMP87CM40ANG-7A46 | ⚡ UCC284DP-ADJ | ⚙️ VI40100C | ➡️ XC61CN3202MRN |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited