


	U479B-MY
	Manufacturer Part Number: U479B-MY
	Manufacturer/Brand: Micrel / Microchip Technology
	Part of Description: IC MON LAMP-OUTAGE 8MV 8DIP
Datasheets:	 U479B-MY.pdf
RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	U479B-MY
Manufacturer	Micrel / Microchip Technology
Description	IC MON LAMP-OUTAGE 8MV 8DIP
Category	Integrated Circuits (ICs) > PMIC - Lighting, Ballast
Part Status	Require For Quote & Check Stock
Series	-
Frequency	-
Current - Supply	4.5mA
Operating Temperature	-40°C ~ 95°C
Mounting Type	Through Hole
Type	Automotive, Lamp Failure
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-DIP
Voltage - Supply	9 V ~ 15 V
Current - Output Source/Sink	-
Dimming	No
Packaging	Tube

U479B-MY is New Original in Stock, Search U479B-MY Datasheets, PDF, Inventory at Y-IC.com Online, Order U479B-MY Micrel / Microchip Technology with warrantied and confidence. RFQ U479B-MY : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>U4793B-MY Micrel / Microchip Technology IC CURRENT MONITOR 8DIP</p>	 <p>U479B-M Micrel / Microchip Technology IC MON LAMP-OUTAGE 8MV 8-DIP</p>	 <p>U479B-MFPY Micrel / Microchip Technology IC MON LAMP-OUTAGE 8MV 8-SOIC</p>	 <p>U479B-MFPG3 Micrel / Microchip Technology IC MON LAMP-OUTAGE 8MV 8-SOIC</p>
 <p>U479B-MFP Micrel / Microchip Technology IC MON LAMP-OUTAGE 8MV 8-SOIC</p>	 <p>U479B-AF SOP SOP TEMIC</p>	 <p>U4793B-MFPY Micrel / Microchip Technology IC CURRENT MONITOR 44MV 8-SOIC</p>	 <p>U479B-MFPY3 ATMEL ATMEL SOP</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|----------------|--------------------|
| 12065A181GA12A | ACE9020B/KG/NP1T | BAR43S-7-F | BF422L-T92-B | CD74HC04E |
| CGA1A2X7R0J103K030BA | CGA5H2X8R1E684K115AA | CGA6M3X8R2A474M200AD | CTT49-08IO1B | DMP3035SFG |
| DS7820AJ/883 | EPM7032LC44-7 | FP-3R0ML102M-GBR | G6SU-2-DC4.5V | GQM1555C2D1R6WB01D |
| HCPL-4506 | HN2C01FU-GR | HZD10-24D05N05 | IP-J11-EX | LTM4618IV#PBF |
| M36W0R5040T7ZAQF | MAX13088EESA+T | MAX1762EUB | MAX488EPA+ | MAZ8390GLL |
| MMB-380V | MN101C35DGD | NJM2375AD | NJU7241F25 | NJU7610RB1-TE1 |
| PD150-N0018 | REF3025AIDBZRG4 | SIHFBC30-E3 | SKMD100/14E | SMCJ33A-E3/57T |
| SML-212DTT86 | SMP1321-001LF | SN74LVC1G373DBVR | SN74LVTH273DBR | SPX385AS-L-1.2/TR |
| SW12PCN030 | TC75S61TU | TC7SA08FU | TNY289KG-TL | TP11MS9ABE |
| TZA1000T/N3 | V300A15C400A | V30200C-E3/4W | VI-JNY-EX | WM8971LEFL/R |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited