










	<h2 style="color: red;">HIP1011DCAZA</h2>	
	Manufacturer Part Number:	HIP1011DCAZA
	Manufacturer/Brand:	Intersil
	Part of Description:	IC CTRLR HOTPLUG PCI DUAL 28SSOP
Datasheets:	 HIP1011DCAZA.pdf	
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications	
Part Number	HIP1011DCAZA
Manufacturer	Intersil
Description	IC CTRLR HOTPLUG PCI DUAL 28SSOP
Category	Integrated Circuits (ICs) > PMIC - Hot Swap Controllers
Part Status	Require For Quote & Check Stock
Series	-
Current - Supply	5.3mA
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Hot Plug Controller
Features	Latched Fault, UVLO
Number of Channels	8
Applications	CompactPCI™
Package / Case	28-SSOP (0.154", 3.90mm Width)
Supplier Device Package	28-SSOP/QSOP
Voltage - Supply	10.8 V ~ 13.2 V
Internal Switch(s)	Both
Programmable Features	Circuit Breaker, Fault Timeout, Slew Rate
Current - Output (Max)	100mA, 500mA
Feature Pins	FLTN, OCSET, PWRON
Packaging	Tube

HIP1011DCAZA is New Original in Stock, Search HIP1011DCAZA Datasheets, PDF, Inventory at Y-IC.com Online, Order HIP1011DCAZA Intersil with warrantied and confidence. RFQ HIP1011DCAZA : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>HIP1011DCA Intersil IC CTRLR HOTPLUG PCI DUAL 28SSOP</p>	 <p>HIP1011DCA-T Intersil IC CTRLR HOTPLUG PCI DUAL 28SSOP</p>	 <p>HIP1011DEVAL1 Intersil EVAL BOARD PCI HOT PLUG DUAL</p>	 <p>HIP1011CBZA-T Intersil IC CTRLR HOT PLUG PCI 16-SOIC</p>
 <p>HIP1011DCAZA-T Intersil IC CTRLR HOTPLUG PCI DUAL 28SSOP</p>	 <p>HIP1011CBZA Intersil IC CTRLR HOT PLUG PCI 16-SOIC</p>	 <p>HIP1011DLA ITS HIP1011DLA ITS</p>	 <p>HIP1011DCAZ INTERSIL HIP1011DCAZ INTERSIL</p>

Hot Parts More

- | | | | | |
|-----------------------|--------------------|----------------------|----------------------------|-------------------|
| ⚙️ 12061A821JAT4A | ➡️ AP130-15WA | ➡️ BTB08-400B | D C0402C0G1C2R2B | ➡️ CCR25.0MUC6AT |
| ⊖ CP1117D50A | ⚙️ EVK105RH3R6JW-F | D GCM1885C1H5R6DA16J | ➡️ GCM219R72A333KA37D | ➡️ GL34A-E3/98 |
| ⚙️ GRM55RR72H333KY21L | ⊖ H0022BNLT | ⚙️ ISL62870HRUZ-T | ➡️ ISPLS12064VE-100LT100DG | ➡️ K0885NG520 |
| D KQT0402TTP7N5J | ⚙️ LM285DG4-1-2 | ⊖ LM3526MX-H | ⚙️ LQH32MN121K01L | ➡️ LT1584CM3.45 |
| ➡️ LT1777IS#PBF | ➡️ MAX211EEAI | ⚙️ MAX4618EPE | ⊖ MAX691ACSE | ➡️ MC14081BD1R2 |
| ➡️ MC34072DR2 | ➡️ MD1501A02PPL | D MDF150A-40L(M) | ⚙️ NCP500SN33T1G | ⊖ NM27LV010BT250 |
| ⚙️ PFE300S-12 | D PIC17C43-16/L | ➡️ PS1101WA-23-TR | ➡️ RP1205-33PBR | ➡️ RT9013-18GU5 |
| ⊖ SKKT213-16E | ⚙️ SPP06N60C3 | ➡️ SZMMSZ36T1G | ➡️ T101F600EGB | ➡️ TBD62064APG |
| ⚙️ TDA1300TT/N1 | ⊖ TM25RZ-2H | ⚙️ TPS62110QRSARQ1 | D TS3V340DGVRG4 | ➡️ TS79L24CS |
| ➡️ TSC5302DCP | ⚙️ VI-204-MX | ⊖ VLF3010AT-220MR33 | ⚙️ VS-45L40 | ➡️ VS-8ETX06FPPBF |