



	<b>DS1812-5+</b>
	<b>Manufacturer Part Number:</b> DS1812-5+
	<b>Manufacturer/Brand:</b> Maxim Integrated
	<b>Part of Description:</b> IC 4.62V P-P 5% TO92-3
<b>Datasheets:</b>	 <a href="#">1.DS1812-5+.pdf</a>
	 <a href="#">2.DS1812-5+.pdf</a>
<b>RoHS Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, 9000 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

### Specifications

Part Number	DS1812-5+
Manufacturer	Maxim Integrated
Description	IC 4.62V P-P 5% TO92-3
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	9000 pcs Stock
Series	EconoReset
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Push-Pull, Totem Pole
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.62V
Packaging	Bulk

DS1812-5+ is New Original in Stock, Search DS1812-5+ Datasheets, PDF, Inventory at Y-IC.com Online, Order DS1812-5+ Maxim Integrated with warrantied and confidence. RFQ DS1812-5+ : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>DS1812-15+</b> Maxim Integrated IC 4.13V P-P 15% TO92-3</p>	 <p><b>DS1812-15/T&amp;R</b> Maxim Integrated IC 4.13V P-P 15% TO92-3</p>	 <p><b>DS18129612A6</b> Original DS18129612A6 Original</p>	 <p><b>DS1812R-10+</b> MAXM DS1812R-10+ MAXM</p>
 <p><b>DS1812R-10+T&amp;R</b> Maxim Integrated IC 4.35V PP 10% SOT23-3</p>	 <p><b>DS1812-15</b> Maxim Integrated IC 4.13V P-P 15% TO92-3</p>	 <p><b>DS1812-5/T&amp;R</b> Maxim Integrated IC 4.62V P-P 5% TO92-3</p>	 <p><b>DS1812-5+T&amp;R</b> Maxim Integrated IC 4.62V P-P 5% TO92-3</p>

### Hot Parts

More

- |                       |                      |                             |                     |                     |
|-----------------------|----------------------|-----------------------------|---------------------|---------------------|
| ⊛ 04025A2R0BAT2A      | ↔ 1206AC391KAZ1A     | ⇒ 251-003/K010-1910/000-200 | D AC0402CRNPO9BN1R2 | ⇒ ADG3242BRJZ-REEL7 |
| ⊣ ADM6825MYRJZ-RL7    | ⊛ AN1200MS-TXL       | D AP1507-33D5-13            | ⇒ AT42QS372-7F5632  | ⇒ AZ431AZ-AE1       |
| ⊛ B82442A1103K        | ⊣ C2012JB1V106K125AC | ⊛ C2220X103K202T            | ↔ CAT24C02WI-GT3    | ⇒ CCP2E45TTE        |
| D CY37256VP208-100NXC | ⊛ ELM7SH08TEL        | ⊣ FDS4885C                  | ⊛ FJPF13007H1TU     | ⇒ GM8182TS-BF       |
| ⇒ GRM0335C1E471GA01D  | ↔ GRM2166R1H390JZ01D | ⊛ GRT31CR61C226ME01L        | ⊣ IPS1051L          | ⇒ IR2304STRPBF      |
| ↔ IR25600STRPBF       | ⇒ IRFU9012PBF        | D ISL54222AIUZ              | ⊛ LB2518T4R7M       | ⊣ LT1507IS8#TRPBF   |
| ⊛ LTC3704EMS#TRPBF    | D MAX3086ESD         | ⇒ MC34064D-5                | ↔ MDC40TA160        | ⇒ NCP584HSN09T1G    |
| ⊣ P140CH02CM0         | ⊛ PI74FCT163244AAX   | ↔ PS2561AL1-1-V-A/JT        | ⇒ RIAQ1639RG        | ⇒ SI3445ADV-T1-E3   |
| ⊛ SK150DAR100D        | ⊣ SMD10L45SP         | ⊛ TLP763JF-F                | D TLV2254AIN        | ⇒ TPS54317RHF       |
| ↔ VE-2N3-IU           | ⊛ VI-243-E           | ⊣ VI-25M-CW                 | ⊛ VI-811589         | ⇒ WM8150CDS/R       |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited