







	TB6552FLG(EL)	
	Manufacturer Part Number:	TB6552FLG(EL)
Manufacturer/Brand:	TOSHIBA	
Part of Description:	TB6552FLG(EL) TOSHIBA	
RoHs Status:		
Stock Condition:	New original, 1980 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	TB6552FLG(EL)
Manufacturer	TOSHIBA
Description	TB6552FLG(EL) TOSHIBA
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1980 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

TB6552FLG(EL) is New Original in Stock, Search TB6552FLG(EL) Datasheets, PDF, Inventory at Y-IC.com Online, Order TB6552FLG(EL) with warrantied and confidence. RFQ TB6552FLG(EL) : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>TB6551FG TOS TB6551FG TOS</p>	 <p>TB6552FNG,C,8,EL Toshiba Semiconductor and Storage IC MOTOR DRIVER PAR 16SSOP</p>	 <p>TB6552FL TOS TB6552FL TOS</p>	 <p>TB6551FG(O,EL,DRY) Toshiba Semiconductor and Storage IC MOTOR CONTROLLER PAR 24SSOP</p>
 <p>TB6552FN Toshiba Semiconductor and Storage TB6552FN TOSHIBA</p>	 <p>TB6552FLG TOS TOS QFN</p>	 <p>TB6552FTG,8,EL Toshiba Semiconductor and Storage IC MOTOR DRIVER PAR 16WQFN</p>	 <p>TB6552FNG TOSHIBA TOSHIBA SSOP16</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|-------------------|-------------------|----------------------|
| ⚙ 25Q1218BVFG | ➡ ACPM-7371 | ➡ ACR25U08LG | D ATC800B4R7BT | ➡ AUIRF1404ZSTRR |
| ⚡ BFR93AWE6587 | ⚙ BKO-C1945H01 | D BT471KPJ66 | ➡ BZT52C9V1Q | ➡ CAB4AZNRR |
| ⚙ CY7C131-35JCT | ⚡ DSS4160V-7 | ⚙ EGP50C-E3/54 | ➡ FM803MS3X | ➡ GP2M020A050H |
| D GRJ31MR71H104KE01L | ⚙ GRM31MR71E225KA93L | ⚡ HHM2227SA1 | ⚙ HI1608-1B4N7SNT | ➡ HX1001-AES |
| ➡ ID9309-33B30R | ➡ IRG4BC10SD | ⚙ JMK063C6104KP-F | ⚡ LM2611BMFX/NOPB | ➡ LM7131BCM/NOPB |
| ➡ LQP15MN18NG02D | ➡ LTC1504IS8 | D LTC3557EUF | ⚙ LTC3717EGN#PBF | ⚡ MB88342PF-G-BND-TR |
| ⚙ MIC2559BM | D MIC7122BMM | ➡ MRFIC2404R2 | ➡ NRF51422-QFAA-T | ➡ PM30RHC060-5 |
| ⚡ S560-6600-DJ-F | ⚙ SBL1635PT | ➡ SFHG00YA002 | ➡ SI-50158-F | ➡ TD240N36KOF |
| ⚙ TMP411BDGKR | ⚡ TSOP85536TR | ⚙ V20150C-E3 | D VI-2NM-IU | ➡ VI-JTZ-MX |
| ➡ VOS617A-3X001T | ⚙ VS-30ETH06STRLPBF | ⚡ XC17S30XLPD8C | ⚙ XJRWD2922 | ➡ ZX5T1951GTA |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited