




	IXS839AQ2
	Manufacturer Part Number: IXS839AQ2
	Manufacturer/Brand: IXYS Corporation
	Part of Description: IC MOSFET DRIVER SYNC BUCK 10QFN
Datasheets:	 IXS839AQ2.pdf
RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

Specifications	
Part Number	IXS839AQ2
Manufacturer	IXYS Corporation
Description	IC MOSFET DRIVER SYNC BUCK 10QFN
Category	Integrated Circuits (ICs) > PMIC - Gate Drivers
Part Status	Require For Quote & Check Stock
Series	-
Input Type	Non-Inverting
Operating Temperature	-40°C ~ 125°C (TJ)
Mounting Type	Surface Mount
Package / Case	10-VFQFN Exposed Pad
Supplier Device Package	10-QFN (3x3)
Voltage - Supply	4.5 V ~ 5.5 V
Channel Type	Synchronous
Driven Configuration	Half-Bridge
Number of Drivers	2
Gate Type	N-Channel MOSFET
Logic Voltage - VIL, VIH	0.8V, 2V
Current - Peak Output (Source, Sink)	2A, 4A
Rise / Fall Time (Typ)	20ns, 15ns
High Side Voltage - Max (Bootstrap)	24V
Packaging	Tube

IXS839AQ2 is New Original in Stock, Search IXS839AQ2 Datasheets, PDF, Inventory at Y-IC.com Online, Order IXS839AQ2 IXYS Corporation with warrantied and confidence. RFQ IXS839AQ2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>IXS839S1T/R IXYS Corporation IC MOSFET DRIVER SYNC BUCK 8SOIC</p>	 <p>IXS839S1 IXYS Corporation IC MOSFET DRIVER SYNC BUCK 8SOIC</p>	 <p>IXSH10N120AU1 IXYS IXSH10N120AU1 IXYS</p>	 <p>IXSA10N60B2D1 IXYS Corporation IGBT 600V 20A 100W TO263</p>
 <p>IXS839BQ2T/R IXYS Corporation IC MOSFET DRIVER SYNC BUCK 10QFN</p>	 <p>IXSA20N60B2D1 IXYS Corporation IGBT 600V 35A 190W TO263</p>	 <p>IXS839AQ2T/R IXYS Corporation IC MOSFET DRIVER SYNC BUCK 10QFN</p>	 <p>IXS839BQ2 IXYS Corporation IC MOSFET DRIVER SYNC BUCK 10QFN</p>

Hot Parts

More

- | | | | | |
|----------------------|---------------------|-----------------------|--------------------------|--------------------|
| ⊛ 04025A240JAT4A | ↔ 06033A100KAT4A | ⇒ 06035C103KA76A | D 08055A7R0KAT4A | ↔ 08055C332JA12A |
| ⊣ A358S06TCF | ⊛ AAT3238IJS-1.5-T1 | D AD7816ARMZ-REEL7 | ⇒ AT27C512R-70JC | ↔ AT49BV322AT-70CI |
| ⊛ BVZ55-B16 | ⊣ C0805C101J1GA7800 | ⊛ C3225X7R2J473K200AA | ↔ CGA2B2X7R1H681K050BA | ↔ D1809N4000T |
| D DN2530N3-G | ⊛ DS1338Z-33 | ⊣ EMD4DXV6T1G | ⊛ FDB035AN06A0 | ↔ FQD5N60C |
| ⇒ GCJ216R71H682KA01D | ↔ H71101516S | ⊛ HDSP-7803 | ⊣ IPB50R250CP | ↔ IRFB38N20DPBF |
| ↔ M34286G2GP | ⇒ MB90F476APFV-G | D MIC811SUYTR | ⊛ N3839TC350 | ⊣ NFE61HT101Z1A9L |
| ⊛ NJM2366V | D P569F3101 | ⇒ PI5A4624CX | ↔ PS9818-2-F3-A | ↔ PVM4A205C01R00 |
| ⊣ S-817A30ANB-CUTT2G | ⊛ SI3201-B5 | ↔ SI9424DY-T1 | ⇒ SKD51/18 | ↔ SS3P4LHM3/86A |
| ⊛ TC1271SERCTR | ⊣ TL431BIDR | ⊛ UPD160705NL | D UPD70F3612M2GAA-GAN-AX | ↔ V48C48M150B |
| ↔ VE-224-CX | ⊛ VT22030A | ⊣ WM8960CGEFL/RV | ⊛ XC6221A302NR | ↔ ZUW64812 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited