

 <p>A Renesas Company</p>	<h2 style="color: red;">X5323V14IT1</h2>	
	<p>Manufacturer Part Number: X5323V14IT1</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p>Datasheets:  X5323V14IT1.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>	
<p>Image may be representation. See specs for product details.</p>		









Specifications

Part Number	X5323V14IT1
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tape & Reel (TR)

X5323V14IT1 is New Original in Stock, Search X5323V14IT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323V14IT1 Intersil with warrantied and confidence. RFQ X5323V14IT1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5323V14T1 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14I-2.7A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5325P Intersil IC CPU SUPRV 32K EE RST HI 8DIP</p>	 <p>X5323ZI INTERMIL X5323ZI INTERMIL</p>
 <p>X5323V14I-4.5A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14I-2.7 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14I Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5325P-2.7 Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>

Hot Parts

More

- | | | | | |
|-------------------|-----------------|--------------------|-----------------------|------------------|
| 06031C103KAT4A | 0603ZD104KAT2A | 170M4264 | D 1808CA470MATME | 1888247-1 |
| ACL3225S-68NM-T | AM27C020-90DC | D B72660M131K72 | BUK416-100AE | BZD27C110P-E3-08 |
| CL21C121JDCNNNC | DCP012415DBP-U | DF200FA80 | DMN6040SVTQ-7 | EL7520AIL |
| D EVK105CH0R5BW-F | FQD1N60TF | GJM0335C1E8R0CB01D | GRM1555C1H101FZ01J | IRF7106TR |
| IRF7321D2TRPBF | IRFI9610G | IRLR7811WTR | LCMXO1200C-4TN144C-3I | LD051A102JAB4A |
| LM2901DR | LP3986-33B3F | LTC5598IUF#PBF | MAX941EUA+ | MICRON38 |
| MM74HC154MTCX | PKG4623PI | PS7341CL-2A | R2J20071BNS | RLZTE-1122D |
| SEP24-8R4 | SH8K2TB1 | SI-5003X-TL | SI7892BDP-T1-GE3 | SKIM271GD128D |
| SKKT250/08D | SN75DP130DSRGZR | SRF10200CT | TK16A60W | TSC2003IZQCR |
| UDQ2982LWTR-T | VI-J6Y-MZ | VOS618A-3X001T | VS-48CTQ060PBF | ZRC330N803TA |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited