


 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">DR127-2R0</h2>
	<p>Manufacturer Part Number: DR127-2R0</p> <p>Manufacturer/Brand: SUMIDA</p> <p>Part of Description: DR127-2R0 SUMIDA</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 244 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	DR127-2R0
Manufacturer	SUMIDA
Description	DR127-2R0 SUMIDA
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	244 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

DR127-2R0 is New Original in Stock, Search DR127-2R0 Datasheets, PDF, Inventory at Y-IC.com Online, Order DR127-2R0 with warrantied and confidence. RFQ DR127-2R0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>DR127-331-R Bussmann (Eaton) FIXED IND 330UH 1.04A 574 MOHM</p>	 <p>DR127-1R5-R Bussmann (Eaton) FIXED IND 1.5UH 13.5A 3.41 MOHM</p>	 <p>DR127-221-R Bussmann (Eaton) FIXED IND 220UH 1.29A 376 MOHM</p>	 <p>DR127-330-R Bussmann (Eaton) FIXED IND 33UH 3.23A 60 MOHM SMD</p>
 <p>DR127-2R2-R Bussmann (Eaton) FIXED IND 2.2UH 12.5A 4.02 MOHM</p>	 <p>DR127-3R3 Bussmann (Eaton) FIXED IND 3.3UH 10.5A 5.67 MOHM</p>	 <p>DR127-271-R Bussmann (Eaton) IND DR127 STYLE 270UH 1.1ARMS 2.</p>	 <p>DR127-220-R Bussmann (Eaton) FIXED IND 22UH 4A 39.1 MOHM SMD</p>

Hot Parts More

- | | | | | |
|-----------------------|--------------------|--------------------|-----------------------|------------------------|
| ⚙️ 08055C220JAT2A | ⚡ A6110K5R-ADJA | ➡️ AOK75B65H1 | D AP78L05YG-13 | ➡️ AX1007E33A |
| ⚡ B39941-B8605-P810 | ⚙️ BLM21A102SPT | D BQ24315DSGR | ➡️ C3225JB2A105K200AA | ➡️ C3225X7S2A335K200AB |
| ⚙️ CHT2312GP | ⚡ CMDSH-3TR | ⚙️ CY2302SC-1T | ⚡ DG201DQ-T1-E3 | ➡️ DP2012-E2455DAT/LF |
| D DRV8837CDSGR | ⚙️ FB15R06KL4-B1 | ⚡ FQA34N20 | ⚙️ FW82803AA | ➡️ GR343DD72J683KW01L |
| ➡️ GRM1555C1H7R8CZ01D | ⚡ HMPP-3890-TR1 | ⚙️ HP5013M28E | ⚡ KIA78DM025F-RTF/PD | ➡️ KS200A800V |
| ⚡ LMV932IDGKR | ➡️ LP3882ES-1.2 | D MAX1897EGP | ⚙️ MAX4117ESA+T | ⚡ MAX973ESA+T |
| ⚙️ MAZ8036GLL | D MBF28A1F06A | ➡️ NNCD6.2D-T1 | ⚡ NSL-06-001 | ➡️ P300CH10FH0 |
| ⚡ PT9161-19CX | ⚙️ S-L2985A18-H4T1 | ⚡ SAFC1489MA70S-TC | ➡️ SI4403BDY-T1-E3 | ➡️ SMBJ54A-E3/52 |
| ⚙️ SMLX14WBETW13Z1 | ⚡ SN74F245N | ⚙️ SN75240P | D SSM3K102TU | ➡️ TLV320ADC3101IRGET |
| ⚡ TPS22913BYZR | ⚙️ TPS54312PWPR | ⚡ UC2842BDG | ⚙️ VI-24L-M | ➡️ XC95108-10TQG100C |