


	<p>BU4213F-TR</p>
	<p>Manufacturer Part Number: BU4213F-TR</p> <p>Manufacturer/Brand: LAPIS Semiconductor</p> <p>Part of Description: IC DETECTOR VOLT 1.3V ODRN 4SOP</p> <p>Datasheets:  BU4213F-TR.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	BU4213F-TR
Manufacturer	LAPIS Semiconductor
Description	IC DETECTOR VOLT 1.3V ODRN 4SOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-82
Supplier Device Package	4-SOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.3V
Packaging	Tape & Reel (TR)

BU4213F-TR is New Original in Stock, Search BU4213F-TR Datasheets, PDF, Inventory at Y-IC.com Online, Order BU4213F-TR LAPIS Semiconductor with warrantied and confidence. RFQ BU4213F-TR : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>BU4213G ROHM BU4213G ROHM</p>	 <p>BU4211GTR ROHM ROHM SMD</p>	 <p>BU4213G-TR LAPIS Semiconductor IC DETECTOR VOLT 1.3V ODRN 5SSOP</p>	 <p>BU4211G-TR LAPIS Semiconductor IC DETECTOR VOLT 1.1V ODRN 5SSOP</p>
 <p>BU4213FVE-TR LAPIS Semiconductor IC DETECTOR VOLT 1.3V ODRN 5VSOF</p>	 <p>BU4212G-TR LAPIS Semiconductor IC DETECTOR VOLT 1.2V ODRN 5SSOP</p>	 <p>BU4214F-TR LAPIS Semiconductor IC DETECTOR VOLT 1.4V ODRN 4SOP</p>	 <p>BU4214FVE-TR LAPIS Semiconductor IC DETECTOR VOLT 1.4V ODRN 5VSOF</p>

Hot Parts

[More](#)

- | | | | | |
|---|--|--|---|--|
|  08055A131JAT2A |  08055A381FAT2A |  12065C221KAT4A |  AO6401AL |  AP2511FGE-7 |
|  AP6203L-18GA |  AT24C02BN-10SU1.8 |  ATIC39S2B2 |  B72214S750K551 |  BLM11B252SDPTM |
|  BSC119N03S |  C1005JB1C154M050BB |  C1005X5R0G225K050BB |  CY62256NL-70SNXI |  D5V0F4U6S-7 |
|  DMA9640MOR |  GRM1555C1H8R7WZ01D |  GRM1887U2AR70CD01D |  HEF4030BT |  HMC596LP4ETR |
|  IP4775CGNPO |  IR1169STRPBF |  IRKC166/16 |  IRKJ56/04 |  IRKT142/20 |
|  IS42S83200B-6TL |  IXDF404SIA-16 |  LC75813TS-E |  LMK212B7684KG-T |  LMV393QDRQ1 |
|  LTC6256CTS8#TRPBF |  LX1688CPW |  MB95009BLPU-G-401-EFE1 |  MC33341DR2G |  NC7SZ34UCX |
|  OPA2363AIDGSR |  OPA2822E |  PI2PCIE412-DZHEX |  PSR-BD01-024-05 |  R2J20751NP#G0 |
|  SC4626LSKTRT |  SKY77149-14 |  SMCJ85CA |  SPC5634MF2MMG80 |  STD1NC60 |
|  T9GH0808K2DH |  TC75G08FE |  TK11231B |  TPC8016H |  VI-LU2-IU |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited