

 Not Actual Photo YIC International Co., Limited.	LP3470IM5-2.93													
	<table border="0"> <tr><td>Manufacturer Part Number:</td><td>LP3470IM5-2.93</td></tr> <tr><td>Manufacturer/Brand:</td><td>N/A</td></tr> <tr><td>Part of Description:</td><td>IC CIRCUIT RESET PWR-ON SOT23-5</td></tr> <tr><td>RoHs Status:</td><td>Contains lead / RoHS non-compliant</td></tr> <tr><td>Stock Condition:</td><td>New original, 12640 pcs Stock Available.</td></tr> <tr><td>Ship From:</td><td>Hong Kong</td></tr> <tr><td>Shipment Way:</td><td>DHL/Fedex/TNT/UPS/EMS</td></tr> </table>	Manufacturer Part Number:	LP3470IM5-2.93	Manufacturer/Brand:	N/A	Part of Description:	IC CIRCUIT RESET PWR-ON SOT23-5	RoHs Status:	Contains lead / RoHS non-compliant	Stock Condition:	New original, 12640 pcs Stock Available.	Ship From:	Hong Kong	Shipment Way:
Manufacturer Part Number:	LP3470IM5-2.93													
Manufacturer/Brand:	N/A													
Part of Description:	IC CIRCUIT RESET PWR-ON SOT23-5													
RoHs Status:	Contains lead / RoHS non-compliant													
Stock Condition:	New original, 12640 pcs Stock Available.													
Ship From:	Hong Kong													
Shipment Way:	DHL/Fedex/TNT/UPS/EMS													
Image may be representation. See specs for product details.														

Specifications

Part Number	LP3470IM5-2.93
Manufacturer	N/A
Description	IC CIRCUIT RESET PWR-ON SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	12640 pcs Stock
Voltage - Threshold	2.93V
Type	Simple Reset/Power-On Reset
Supplier Device Package	SOT-23-5
Series	-
Reset Timeout	1 ms Minimum
Reset	Active Low
Packaging	Tape & Reel (TR)
Package / Case	SC-74A, SOT-753
Output	Open Drain or Open Collector
Operating Temperature	-40°C ~ 85°C (TJ)
Number of Voltages Monitored	1
Mounting Type	Surface Mount

LP3470IM5-2.93 Electronic Components is 100% New Original from YIC Distributor, Search LP3470IM5-2.93 Datasheets, PDF, Inventory at Y-IC.com Online, Order LP3470IM5-2.93 with Warrantied and Confidence. Ship by DHL/FedEx/TNT/UPS Express. Support Payment with Telegraphic Transfer(T/T) or PayPal.
RFQ LP3470IM5-2.93 Email: Info@Y-IC.com

You May Be Also Be interested

In:

 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.
LP3470IM5-3.65/NOPB N/A IC CIRCUIT RESET PWR-ON SOT23-5	LP3470IM5-3.65 N/A IC CIRCUIT RESET PWR-ON SOT23-5	LP3470IM5-3.08/NOPB N/A IC CIRCUIT RESET PWR-ON SOT23-5	LP3470IM5-2.75 N/A IC RESET CIRCUIT 2.75V SOT23-5
 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.
LP3470IM5-2.83 N/A IC RESET CIRCUIT 2.83V SOT23-5	LP3470IM5-3.08 N/A IC CIRCUIT RESET PWR-ON SOT23-5	LP3470IM5-2.63/NOPB N/A IC CIRCUIT RESET PWR-ON SOT23-5	LP3470IM5-2.83/NOPB N/A IC RESET CIRCUIT 2.83V SOT23-5

LP3470IM5-2.93 Related keyword

More

LP3470IM5-2.93	LP3470IM5-2.93 Data Sheet	LP3470IM5-2.93 Datasheets	LP3470IM5-2.93 PDF	LP3470IM5-2.93
LP3470IM5-2.93 Electronic	LP3470IM5-2.93 Components	LP3470IM5-2.93 Distributor	LP3470IM5-2.93 Image	LP3470IM5-2.93 Part
LP3470IM5-2.93 Price	LP3470IM5-2.93 Manufacturer	LP3470IM5-2.93 Picture	LP3470IM5-2.93 Stock	LP3470IM5-2.93 Inventory
LP3470IM5-2.93 New	LP3470IM5-2.93 Original	LP3470IM5-2.93 Warranted	LP3470IM5-2.93 RFQ	LP3470IM5-2.93 Order Online

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2020 YIC International Co., Limited