	<h2 style="color: red;">AD5228BUJZ100</h2>
	<p>Manufacturer Part Number: AD5228BUJZ100</p> <p>Manufacturer/Brand: AD</p> <p>Part of Description: AD5228BUJZ100 AD</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 425 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	AD5228BUJZ100
Manufacturer	AD
Description	AD5228BUJZ100 AD
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	425 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

AD5228BUJZ100 is New Original in Stock, Search AD5228BUJZ100 Datasheets, PDF, Inventory at Y-IC.com Online, Order AD5228BUJZ100 with warrantied and confidence. RFQ AD5228BUJZ100 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>AD5228BUJZ100-R2 ADI (Analog Devices, Inc.) IC DGTL POT 100K UP/DN TSOT23-8</p>	 <p>AD5228BUJ50-RL7 AD/AD AD5228BUJ50-RL7 AD/AD</p>	 <p>AD5228BUJZ100-RL7 ADI (Analog Devices, Inc.) IC DGTL POT 32POS 100K TSOT23-8</p>	 <p>AD5228BUJZ10-R2 ADI (Analog Devices, Inc.) IC DGTL POT 10K UP/DN TSOT23-8</p>
 <p>AD5228BUJZ10-RL7 ADI (Analog Devices, Inc.) IC DGTL POT UP/DN 10K TSOT23-8</p>	 <p>AD5228BUJ100-RL7 ADI (Analog Devices, Inc.) AD5228BUJ100-RL7 AD</p>	 <p>AD5228BUJZ50-R2 ADI (Analog Devices, Inc.) IC DGTL POT 50K UP/DN TSOT23-8</p>	 <p>AD5227BUJZ50-RL7 ADI (Analog Devices, Inc.) IC DGTL POT 50K UP/DN TSOT23-8</p>

Hot Parts

[More](#)

- | | | | | |
|---------------------|-----------------------|-----------------------|------------------------|-------------------------|
| ⚙️ 06031A120F4T2A | ➡️ 06031A1R8DAT2A | ➡️ 0603ZA270JAT2A | D 0805YA182GAT2A | ➡️ AD9762AR |
| ⊖ B82498F3120J | ⚙️ BA3129F-T1 | D BA5924FP | ➡️ C0603X5R0J104K030BC | ➡️ C1005NP01H150J050BA |
| ⚙️ C3225Y5V1E106Z/5 | ⊖ CAT25010VP2I-GT3 | ⚙️ CSTCW48M0X11038-R0 | ➡️ CY62256LL-70SNXC | ➡️ DSC1033DI2-025.0000T |
| D EPM2210F324I5N | ⚙️ FP50R12KT4-B13-ENG | ⊖ GRM022R60J224ME14L | ⚙️ GRM0335C1E6R0DD01D | ➡️ GRM21BR60J106KE19K |
| ➡️ H11N3SR2VM | ➡️ IDT6167SA100DB | ⚙️ IPD068N10N3G | ⊖ IRF6678TRPBF | ➡️ IRF7835TRPBF |
| ➡️ IRLR3715TRL | ➡️ K4E151612D-JC50 | D LM82CIMQAX/NOPB | ⚙️ LQP03TN27NH04D | ⊖ LTC3700EMS#TRPBF. |
| ⚙️ MAX1842EEE-TG096 | D MAX8680ETL+ | ➡️ MAX8715EUA+ | ➡️ MAZ31300ML | ➡️ MB87S1092BGL-GE1 |
| ⊖ MM3Z5V6C | ⚙️ MMSZ5257BS | ➡️ MSM5416258B-45TS-K | ➡️ NCP698SQ30T1G | ➡️ OB3393SCPA |
| ⚙️ PSR-BD01-024-12 | ⊖ S-80727AN-DQ-T1 | ⚙️ SKKH92/16E | D SKT240F08DT | ➡️ STD38NH02LT4 |
| ➡️ TPS71712DCKRG4 | ⚙️ VE-2N0-MV | ⊖ VI-JT4-MY | ⚙️ VR8-9250-10800T | ➡️ ZXMN2088DE6TA |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited