



 <p>A Renesas Company</p>	<p><b>HI1-0508-5</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">HI1-0508-5</a></p> <hr/> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <hr/> <p><b>Part of Description:</b> IC MULTIPLEXER 8X1 16CDIP</p> <hr/> <p><b>Datasheets:</b>  <a href="#">HI1-0508-5.pdf</a></p> <hr/> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <hr/> <p><b>Stock Condition:</b> New original, 31 pcs Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	HI1-0508-5
Manufacturer	Intersil
Description	IC MULTIPLEXER 8X1 16CDIP
Category	Integrated Circuits (ICs) > Interface - Analog Switches,
Part Status	31 pcs Stock
Series	-
Operating Temperature	0°C ~ 75°C (TA)
Package / Case	16-CDIP (0.300", 7.62mm)
Supplier Device Package	16-CDIP
Number of Circuits	1
-3db Bandwidth	-
Multiplexer/Demultiplexer Circuit	8:1
Switch Circuit	-
On-State Resistance (Max)	400 Ohm
Voltage - Supply, Single (V+)	-
Voltage - Supply, Dual (V±)	±15V
Channel-to-Channel Matching (ΔRon)	20 Ohm
Switch Time (Ton, Toff) (Max)	250ns, 250ns (Typ)
Charge Injection	-
Channel Capacitance (CS(off), CD(off))	10pF, 17pF
Current - Leakage (IS(off)) (Max)	30pA (Typ)
Crosstalk	-
Packaging	Tube

HI1-0508-5 is New Original in Stock, Search HI1-0508-5 Datasheets, PDF, Inventory at Y-IC.com Online, Order HI1-0508-5 Intersil with warrantied and confidence. RFQ HI1-0508-5 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

You May Be Also Be interested

<p>In:</p>  <p><b>HI1-0508DM</b> N/A HI1-0508DM N/A</p>	 <p><b>HI1-0506A/883</b> INTERSI INTERSI CDIP</p>	 <p><b>HI1-0508-2</b> Intersil IC MULTIPLEXER 8X1 16CDIP</p>	 <p><b>HI1-0508A-2</b> INTERSI INTERSI CDIP</p>
 <p><b>HI1-0508A-2</b> Maxim Integrated IC MULTIPLEXER 8X1 16CDIP</p>	 <p><b>HI1-0507A/883</b> INTERSI INTERSI CDIP</p>	 <p><b>HI1-0508A-8</b> INTERSI HI1-0508A-8 INTERSI</p>	 <p><b>HI1-0507/883</b> INTERSI INTERSI CDIP</p>

Hot Parts

More

- |                    |                      |                |                      |                      |
|--------------------|----------------------|----------------|----------------------|----------------------|
| AA4005GTR-E1       | AH287-YL-AS          | B82793S513N    | CGA4J2C0G1H103J      | CL03B821K03NNNC      |
| CL31B102MJHNNNE    | CX2520DB38400D0FLJZ1 | DS1608BL-684C  | EC20QS06             | ESD5V3L1B-02LS       |
| FMMTA43R           | GJM1555C1H1R0BB01J   | H11SADXM_5676D | HY29LV160BT-12W      | IAM82008TR1          |
| IMP813LCUA/T       | INA220BQDGSRQ1       | IPA65R380E6    | IQ221205             | IS45S16100C1-7BLA1-T |
| ISL97649BIRZ       | LC4128C-75TN128-10I  | LD053A121JAB2A | LT1767EMS8-1.8#TRPBF | LTC6256CMS8#TRPBF    |
| MAX14885EETL+T     | MAX4251ESA           | MJH11021       | N510CH20KOO          | NTR1P02T3G           |
| P0306SC08A         | PIC12C509A-04/SM     | PRN300BB20     | RF2705TR13           | S-1323B29NB-N80-TF   |
| SIR800DP-T1-E3     | SKBH28-14            | SKiiP32UPS06   | SKKT26/08D           | SN74ABT162245DL      |
| T520V157M006ATE045 | TCR3DF29             | TMG10C60F      | TZMC3V3-GS18         | UMX18NTN             |
| V48A3V3C264AL2     | W0614WC40            | XI-260-MU      | XIO2200A             | ZXM64N02             |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited