


	<h2 style="color: #e67e22;">AD9522-5BCPZ</h2>
	<p>Manufacturer Part Number: AD9522-5BCPZ</p> <hr/> <p>Manufacturer/Brand: ADI (Analog Devices, Inc.)</p> <hr/> <p>Part of Description: IC CLOCK GEN 2.4GHZ 64LFCSP</p> <hr/> <p>Datasheets:  AD9522-5BCPZ.pdf</p> <hr/> <p>RoHs Status:  Lead free / RoHS</p> <hr/> <p>Stock Condition: Compliant New original, 5 pcs Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	AD9522-5BCPZ
Manufacturer	ADI (Analog Devices, Inc.)
Description	IC CLOCK GEN 2.4GHZ 64LFCSP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	5 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Clock Generator, Fanout Distribution
Frequency - Max	2.4GHz
Package / Case	64-VFQFN Exposed Pad, CSP
Supplier Device Package	64-LFCSP-VQ (9x9)
Number of Circuits	1
Voltage - Supply	3.135 V ~ 3.465 V
Output	CMOS, LVDS, LVPECL
Input	CMOS, LVDS, LVPECL
PLL	Yes
Ratio - Input:Output	2:12, 2:24
Differential - Input:Output	Yes/Yes
Divider/Multiplier	Yes/No
Packaging	Tray

AD9522-5BCPZ is New Original in Stock, Search AD9522-5BCPZ Datasheets, PDF, Inventory at Y-IC.com Online, Order AD9522-5BCPZ ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ AD9522-5BCPZ : Info@Y-IC.com



You May Be Also Be interested

In:

 <p>AD9523-1/PCBZ ADI (Analog Devices, Inc.) BOARD EVAL FOR AD9523-1</p>	 <p>AD9522-4/PCBZ ADI (Analog Devices, Inc.) BOARD EVAL FOR AD9522-4 CLK GEN</p>	 <p>AD9522-5BCPZ-REEL7 ADI (Analog Devices, Inc.) IC CLOCK GEN 2.4GHZ 64LFCSP</p>	 <p>AD9522-4BCPZ ADI (Analog Devices, Inc.) IC CLOCK GEN 1.6GHZ VCO 64LFCSP</p>
 <p>AD9523-1BCPZ ADI (Analog Devices, Inc.) IC INTEGER-N CLCK GEN 72LFCSP</p>	 <p>AD9522-4BCPZ-REEL7 ADI (Analog Devices, Inc.) IC CLOCK GEN 1.6GHZ VCO 64LFCSP</p>	 <p>AD9522-3BCPZ-REEL7 ADI (Analog Devices, Inc.) IC CLOCK GEN 2GHZ VCO 64LFCSP</p>	 <p>AD9523-1BCPZ-REEL7 ADI (Analog Devices, Inc.) IC INTEGER-N CLCK GEN 72LFCSP</p>

Hot Parts

More

- | | | | | |
|--|--|---|--|--|
|  150K180A |  1812CC333MAT1A |  1812JA270JAT1A\SB |  D 1N4748A-TAP |  AL1696-30AS7-13 |
|  AP4424GM-HF |  ATTINY12L-4SU |  D BSF050N03LQ3G |  CC0201KRX7R7BB332 |  CD74HCT4538M96 |
|  CDRH5D18NP-220NC |  DC280-15 |  DN8899UAESE1V |  FAN54015UCX |  FDD14AN06LAO |
|  D FDW2504P |  GRM1885C2A7R0CA01D |  HCF4025BEY |  HT82K96E |  IP5002CX8 |
|  ISL6292CCR3Z |  LD06CC472KAB1A |  LL1608-FH2N7S |  LM317EMP |  LM4132DMF-2.5/NOPB |
|  LMSP2PQP-G92 |  LP3470M5X-4.63 |  D LT3972EMSE#PBF |  LTC6253CMS8#TRPBF |  MAX4104ESA+ |
|  MCZ33975EK |  D MT66R7072A10AB5ZZW.ZCA |  NFM21HC102R1H3D |  NTSAF5100 |  SBR10200CTFP |
|  SE5515A-R |  SKKH131-16E(D) |  SKNH132/14E |  SMDJ33A-HRA |  STD17NF25T4 |
|  STK0160LM |  STLCS465C |  T46F600CEC |  D TC7SG126AFS |  TDA5144AT |
|  TPS61043DRBRG4 |  U4311B-CFLG3 |  VD241212H-1W |  VI-231-E |  W0735SA150 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited