 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">HAL-546SF-K-4-R-1-00-HASE</h2>
	<p>Manufacturer Part Number: HAL-546SF-K-4-R-1-00-HASE</p> <p>Manufacturer/Brand: MICRONAS</p> <p>Part of Description: HAL-546SF-K-4-R-1-00-HASE MICRONAS</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 809 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	HAL-546SF-K-4-R-1-00-HASE
Manufacturer	MICRONAS
Description	HAL-546SF-K-4-R-1-00-HASE MICRONAS
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	809 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

HAL-546SF-K-4-R-1-00-HASE is New Original in Stock, Search HAL-546SF-K-4-R-1-00-HASE Datasheets, PDF, Inventory at Y-IC.com Online, Order HAL-546SF-K-4-R-1-00-HASE with warrantied and confidence. RFQ HAL-546SF-K-4-R-1-00-HASE : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>HAL APV V5.1 Micronas BOARD PROGRAMR HAL8 HAL100 CUR31</p>	 <p>HAL1000UT-A-2-A MICRONA HAL1000UT-A-2-A MICRONA</p>	 <p>HAL USB PROGRAMMER TOOL V.1.0 Micronas BOARD USB PROGRAMMER HALL SENSOR</p>	 <p>HAL APB V1.5 Micronas BOARD PROGRAMMER APB V1.5 SENSOR</p>
 <p>HAL1000UT-A Micronas TO92-UT</p>	 <p>HAL1000UT-K Micronas TO92-UT</p>	 <p>HAL 600-S LEM USA, Inc. SENSOR CURRENT HALL 600A AC/DC</p>	 <p>HAL 500-S LEM USA, Inc. SENSOR CURRENT HALL 500A AC/DC</p>

Hot Parts

[More](#)

- | | | | | |
|---------------------|-----------------------|-------------------------|----------------------|----------------------|
| ⚙️ 06033C122JAT2A | ➡️ 6FLR20S02 | ➡️ AD5160BRJ100-RL7 | D AD8604DRZ-REEL7 | ➡️ ADPD142RG-BCEZ-RL |
| ⚡ AM3456NE-T1-PF | ⚙️ AP2113BMTR-G1 | D APTGT400U120D4 | ➡️ BCR12PM-12 | ➡️ BD4850G-GTR |
| ⚙️ BULLETIN150 | ⚡ C0402C0G1C1R1C | ⚙️ CGA2B3X5R1V683K050BB | ➡️ CMHZ5263B | ➡️ D348S16T |
| D DTDG23YP | ⚙️ E28F020-90 | ⚡ FAN5032MPX | ⚙️ FAN53418MX | ➡️ FDB16AN08A0 |
| ➡️ FIAM1M53 | ➡️ GRM0225C1E6R4DDAEL | ⚙️ HNC151-100 | ⚡ HSMD-A100-J00J1 | ➡️ IRFIZ34N |
| ➡️ LM1117IDT-3.3 | ➡️ LP3917RL-QL/NOPB | D LT1304CS8-3.3#TRPBF | ⚙️ LT1640ALIS8#TRPBF | ⚡ MAX803SEXR+T |
| ⚙️ MBRS320_NL | D MG100G1AL1 | ➡️ PT6913-TP | ➡️ R220CH04FJO | ➡️ S-8250AAE-I6T1U |
| ⚡ S-8330A24FS-T2 | ⚙️ SD603C22S20C | ➡️ SFH691BT | ➡️ SI3500-A-GM | ➡️ SI7464DP-T1-GE3 |
| ⚙️ SKIIP20NAC063IT3 | ⚡ SN74AHCT16244DLR | ⚙️ SPFD3215C-HF021 | D SUCS30515B | ➡️ TMP86FM25FG |
| ➡️ UND-300H/200B | ⚙️ UNR91A3JOL | ⚡ VI-26F-MV | ⚙️ VI-J74-EZ | ➡️ XR3081XID-F |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited