








	<h2 style="color: #D9534F;">MC145158DW2</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">MC145158DW2</a>
	<b>Manufacturer/Brand:</b>	<a href="#">NXP Semiconductors / Freescale</a>
	<b>Part of Description:</b>	IC SER-IN PLL FREQ SYNTH 16-SOIC
<b>Datasheets:</b>	 <a href="#">MC145158DW2.pdf</a>	
<b>RoHs Status:</b>	Contains lead / RoHS non-compliant	
<b>Stock Condition:</b>	New original, 42 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications	
Part Number	<a href="#">MC145158DW2</a>
Manufacturer	<a href="#">NXP Semiconductors / Freescale</a>
Description	IC SER-IN PLL FREQ SYNTH 16-SOIC
Category	<a href="#">Integrated Circuits (ICs) &gt; Clock/Timing - Clock</a>
Part Status	42 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	PLL Clock/Frequency Synthesizer
Frequency - Max	25MHz
Package / Case	16-SOIC (0.295", 7.50mm Width)
Supplier Device Package	16-SOIC
Number of Circuits	1
Voltage - Supply	3 V ~ 9 V
Output	Clock
Input	Clock
PLL	Yes
Ratio - Input:Output	1:1
Differential - Input:Output	No/No
Divider/Multiplier	Yes/No
Packaging	Tube





























MC145158DW2 is New Original in Stock, Search MC145158DW2 Datasheets, PDF, Inventory at Y-IC.com Online, Order MC145158DW2 NXP Semiconductors / Freescale with warrantied and confidence. RFQ MC145158DW2 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

You May Be Also Be interested

<p><b>In:</b></p>  <p><b>MC145158-2</b> FREESCA MC145158-2 FREESCA</p>	 <p><b>MC145158P1</b> MOT MC145158P1 MOT</p>	 <p><b>MC145158DW-2</b> MOT MC145158DW-2 MOT</p>	 <p><b>MC145159DW1</b> MOTOROLA MOTOROLA SOP20</p>
 <p><b>MC145159DW</b> MOT MC145159DW MOT</p>	 <p><b>MC145157P2</b> MOT MC145157P2 MOT</p>	 <p><b>MC145157PI</b> MOTOROLA MC145157PI MOTOROLA</p>	 <p><b>MC145158DW</b> MOT MOT SOP-16</p>

Hot Parts

More

- |  |   |  |  |   |
|--|---|--|--|---|
|  1206AA101JAT1A       |  293D476X06R3C2TE3   |  ACPL-339J          |  D AD8302ARUZ        |  AD9231BCPZ-40   |
|  ADG222TE/883B        |  AP50T10GH           |  D ATTINY13V-10MU   |  BS86D20A-3          |  BYM07-E3/82     |
|  C1005CH1H181K050BA   |  C1005X7R1H682K050BA |  C1PM30A7           |  C4532X7R2E474K230KE |  EL5129IREZ      |
|  D GRM0225C1E5R6WA03L |  GRM1882C1H300JA01D  |  IR3856MTR1PBF.     |  IRKC56/14A          |  K4D263238E-GC36 |
|  L6928D013TR          |  LM2755TMX           |  LM4040DIZ-1.2      |  M25PX64-VMF6TP      |  MAX4634EUB+     |
|  MIC4428CM            |  N0416SG060          |  D NP50P04SDG-E2-AY |  NTTS2P02R2          |  PAH75S48-3.3/V  |
|  PDS560-13            |  PQ07VR5MAP          |  RB520S30T/R        |  RUR020N02TL         |  SFH615A-2X009   |
|  SFHG52AA002          |  SI7222DN-T1-E3      |  SKKT55/12H3        |  SPMC65SF112A        |  SPN7510T220TGB  |
|  STP60N06-14          |  SUD45P03-15-T1-E3   |  T491D685M050AT     |  TK11130M-TL         |  TK11535MTL      |
|  TLE8088EM            |  TLV431BE5TA         |  TPA2055D3YZNR      |  UMK325BJ475MNHT     |  YS570101-P18    |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited