









	<h2 style="color: #E67E22;">ADF5355BCPZ</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">ADF5355BCPZ</a>
	<b>Manufacturer/Brand:</b>	<a href="#">ADI (Analog Devices, Inc.)</a>
	<b>Part of Description:</b>	IC INTEGRATED SYNTH/VCO 32LFCSP
<b>Datasheets:</b>	 <a href="#">ADF5355BCPZ.pdf</a>	
<b>RoHs Status:</b>	 Lead free / RoHS	
<b>Stock Condition:</b>	Compliant New original, 700 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	ADF5355BCPZ
Manufacturer	ADI (Analog Devices, Inc.)
Description	IC INTEGRATED SYNTH/VCO 32LFCSP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	700 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Frequency - Max	13.6GHz
Package / Case	32-WFQFN Exposed Pad, CSP
Supplier Device Package	32-LFCSP-WQ (5x5)
Number of Circuits	1
Voltage - Supply	3.15 V ~ 3.45 V
Output	Clock
Input	Clock
PLL	No
Ratio - Input:Output	1:2
Differential - Input:Output	Yes/Yes
Divider/Multiplier	Yes/Yes
Packaging	Tray

ADF5355BCPZ is New Original in Stock, Search ADF5355BCPZ Datasheets, PDF, Inventory at Y-IC.com Online, Order ADF5355BCPZ ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ ADF5355BCPZ : Info@Y-IC.com

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>ADF5356BCPZ</b> ADI (Analog Devices, Inc.) 13.6GHZ PLLVCO(UPGRADE OF ADF535)</p>	 <p><b>ADF50NFN</b> JPC JPC DIP-8</p>	 <p><b>ADF5356BCPZ-RL7</b> ADI (Analog Devices, Inc.) 13.6GHZ PLLVCO(UPGRADE OF ADF535)</p>	 <p><b>ADF5901ACPZ</b> ADI (Analog Devices, Inc.) 24GHZ TX MMIC: VCO_PGA+ DUAL PA</p>
 <p><b>ADF5001BCPZ-RL7</b> ADI (Analog Devices, Inc.) IC PRESCALER 4-18GHZ LN 16LFCSP</p>	 <p><b>ADF5355BCPZ-RL7</b> ADI (Analog Devices, Inc.) IC INTEGRATED SYNTH/VCO 32LFCSP</p>	 <p><b>ADF5901ACPZ-RL7</b> ADI (Analog Devices, Inc.) 24GHZ TX MMIC: VCO_PGA+ DUAL PA</p>	 <p><b>ADF5002BCPZ-RL7</b> ADI (Analog Devices, Inc.) IC PRESCALER 18GHZ 16LFCSP</p>

### Hot Parts

More

- |                     |                   |                      |                      |                        |
|---------------------|-------------------|----------------------|----------------------|------------------------|
| ⊕ 06035C361KAT2A    | ↔ 12065C272JAT2A  | ⇒ ACS704ELC-005      | D AD7804BR           | ↗ AP6213A-12NHFGA      |
| ⊖ AQY284EHAX        | ⊕ BCM5464RA1KFBG  | D BZD27C22P-E3-08    | ⇒ C0805C104K5RAC     | ↗ CGA4J4C0G2W332J125AA |
| ⊕ CY7C026AV-25AXC   | ⊖ CY7C64113-PVCG  | ⊕ EMK063B7331KP-F    | ↔ FCP11N60F          | ↗ FD400R12KE3_B5       |
| D FDC6302P-NL       | ⊕ FPD750SOT892    | ⊖ GCM2165C1H221JA16D | ⊕ GRM0335C1E7R8DD01D | ↗ HTT250N1000KOB       |
| ⇒ IRU1050-33CDTR    | ↔ KSA1298YMTF     | ⊕ LMV822MMX          | ⊖ LT1117-3.3TR       | ↗ LTC3801BES6          |
| ↔ M2404HEPROM       | ⇒ MAX8878EUK50    | D MF-SM050/60-2-H5   | ⊕ MT47H128M4CF-3:F   | ⊖ N0416SD040           |
| ⊕ NCP512SQ18T1G     | D OZ-SS-112LM1    | ⇒ P0752.104NL        | ↔ PMB4820V1.1        | ↗ PQ40080QGB09NNS-G    |
| ⊖ R4040770          | ⊕ RC0402FR-0715KL | ↔ RCLAMP1624T.TCT    | ⇒ RT9809-26CV        | ↗ SB540A-E3/73         |
| ⊕ SN74ABT16825DLRG4 | ⊖ SN74LVC827APWR  | ⊕ SS10P6-M3/86A      | D ST200S16M          | ↗ STM8AF52A9TAY        |
| ↔ SY89834UMG        | ⊕ T459N24TOC      | ⊖ TLV2462IDGK        | ⊕ TPS7A4515KTTR      | ↗ ZUG2206-11AS         |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited