


	<p>S-80828CLY-B2-U</p>
	<p>Manufacturer Part Number: S-80828CLY-B2-U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 2.8V TO-92</p>
<p>Datasheets:  S-80828CLY-B2-U.pdf</p>	<p>RoHS Status:  Lead free / RoHS</p>
<p>Stock Condition: Compliant New original, Stock Available.</p>	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>




Specifications

Part Number	S-80828CLY-B2-U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 2.8V TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Voltage Detector
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	2.8V
Packaging	Bulk

S-80828CLY-B2-U is New Original in Stock, Search S-80828CLY-B2-U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80828CLY-B2-U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80828CLY-B2-U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80828CLUA-B6NT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.8V SOT89-3</p>	 <p>S-80828CLPF-B6NTFU SII Semiconductor Corporation IC VOLT DETECTOR 2.8V SNT-4A</p>	 <p>S-80828CNMA-B8NT1G SEIKO S-80828CNMA-B8NT1G SEIKO</p>	 <p>S-80828CLY-B-G SII Semiconductor Corporation IC VOLT DETECTOR 2.8V TO-92</p>
 <p>S-80828CLY-Z2-U SII Semiconductor Corporation IC VOLT DETECTOR 2.8V TO-92</p>	 <p>S-80828CLUA-B6NT2G SII Semiconductor Corporation IC VOLT DETECTOR 2.8V SOT89-3</p>	 <p>S-80828CNMC-B8N-T2 SII S-80828CNMC-B8N-T2 SII</p>	 <p>S-80828CNBB SEIKO SEIKO 4-PinSNB(B)</p>

Hot Parts

More

- | | | | | |
|-------------------|-----------------------|--------------------------|--------------------------|-----------------------|
| ⚙️ 06033C104KAJ2A | ➡️ 06033C681JAJ2A | ➡️ 08053G334ZAT2A | D A30Q550-4L | ➡️ AAT3522IGY-3.08-50 |
| ⊖ AD5325ARMZ | ⚙️ AD8565AKSZ | D ADM6319CY26ARJZ-REEL7 | ➡️ ADS7049QDCURQ1 | ➡️ APTCC1184 |
| ⚙️ ATMEGA169V-1AI | ⊖ B59707A0120A062 | ⚙️ CAN4311712002453K | ➡️ CL03A223KP3NNNC | ➡️ CSD17309Q3 |
| D EN12-HS20AF18 | ⚙️ EZ1117ACST-3.3 | ⊖ FDB6030AL | ⚙️ FF600R06ME4 | ➡️ FK20SM-10 |
| ➡️ GIPS20C60 | ➡️ GRJ188R61C105KE11D | ⚙️ GRM0225C1E9R0BA03L | ⊖ HMK316BJ105KL-T | ➡️ IMC1812ER680K |
| ➡️ IRF644PBF | ➡️ IRLZ24LPBF | D KK2500A800V | ⚙️ LM385D-2-5 | ⊖ LMC6034IM |
| ⚙️ LMV821M5X | D M37702E8BFP | ➡️ MB90F947APQCR-GS-SPE2 | ➡️ MCP2210-I/SS | ➡️ MPC8347CVRAGDB |
| ⊖ MSG60J41 | ⚙️ NFZ2BC4W5 | ➡️ NTA1215MC | ➡️ RN142ZST2R | ➡️ SI1972DH-T1-GE |
| ⚙️ SM59064C40J | ⊖ SMD1206P020 | ⚙️ SP7648EJ | D TSM042N03CS | ➡️ V110C12C100BG |
| ➡️ V24C5C50B2 | ⚙️ XC6372D332PR | ⊖ XP0150100L | ⚙️ XPCWHT-L1-7AO-N4-0-01 | ➡️ XRA1202IG16-F |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited