	<b>2SA2122GOLSO</b>	
	<b>Manufacturer Part Number:</b>	2SA2122GOLSO
<b>Manufacturer/Brand:</b>	PANASON	
<b>Part of Description:</b>	PANASON SOT323	
<b>RoHs Status:</b>		
<b>Stock Condition:</b>	New original, 15000 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		









**Specifications**

Part Number	2SA2122GOLSO
Manufacturer	PANASON
Description	PANASON SOT323
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	15000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

2SA2122GOLSO is New Original in Stock, Search 2SA2122GOLSO Datasheets, PDF, Inventory at Y-IC.com Online, Order 2SA2122GOLSO with warrantied and confidence. RFQ 2SA2122GOLSO : Info@Y-IC.com

You May Be Also Be interested

In:

 <b>2SA2122G</b> PANASONIC 2SA2122G PANASONIC	 <b>2SA2125-S-TD-H</b> AMI Semiconductor / ON Semiconductor TRANS PNP 50V 3A	 <b>2SA2124-S-TD-E</b> AMI Semiconductor / ON Semiconductor TRANS PNP 30V 2A	 <b>2SA2122GOLSO+</b> Panason 2SA2122GOLSO+ Panason
 <b>2SA2124-TD-E</b> AMI Semiconductor / ON Semiconductor TRANS PNP 30V 2A SOT89-3	 <b>2SA2122G0L</b> PANASONIC PANASONIC SOT323-6.	 <b>2SA2122DOLO</b> Panasonic 2SA2122DOLO Panasonic	 <b>2SA2122G0LS0</b> Panasonic 2SA2122G0LS0 Panasonic

**Hot Parts**

More

- |                      |                      |                      |                        |                        |
|----------------------|----------------------|----------------------|------------------------|------------------------|
| ⚙️ 08056D105KAT4A    | ➡️ 18125C683KAT2A    | ➡️ 2-2013290-3       | D 2MBI1400VXB-170-54   | ➡️ AD1885JST           |
| ⚡ AP119-89           | ⚙️ AS7C1024B-15TJCTR | D ATT2164AS-TR       | ➡️ C2012X6S1A685K085AC | ➡️ C3216X7R2A105M160AA |
| ⚙️ CDD120-16         | ⚡ DD90N14K           | ⚙️ DNF20-SG-4A       | ➡️ DRV8808DCAR         | ➡️ DS14C89AMX          |
| D EMK316BJ225MD-T    | ⚙️ FC1610-TC-AJ0-01  | ⚡ GRM0225C1E4R9CDAEL | ⚙️ GRM1556P1H5R4DZ01D  | ➡️ GRM1887U1H3R9CZ01D  |
| ➡️ HMK107B7152KA-T   | ➡️ IHW20T120         | ⚙️ IS62LV1024LL-55T  | ⚡ LM339DRG3            | ➡️ LM4863MX            |
| ➡️ LMZ14203HTZE/NOPB | ➡️ LP2950ACZ-3.3G    | D LTC3200ES6-5       | ⚙️ M24256-BVMN6TP      | ⚡ MAAM-011208-TR3000   |
| ⚙️ MAX3223CDBRG4     | D MC10XS3435D        | ➡️ MC33662LEFG       | ➡️ MIC5207YM5-TR       | ➡️ P6SMBJ54A           |
| ⚡ PGH10016           | ⚙️ PSB25/08          | ➡️ QCPL-4651#500     | ➡️ R3111Q351A-TR       | ➡️ SC505834CFUB8       |
| ⚙️ SKT1000/16        | ⚡ TDA9973AHL/8/21    | ⚙️ TESVA0G475        | D TPS2375PWRG4         | ➡️ V62/06632-01XE      |
| ➡️ VI-24L-CV         | ⚙️ WSL2512R0100FTB   | ⚡ XC17V04VQ44I       | ⚙️ XC9226A33CMR        | ➡️ XR16V2550IL         |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited