


 life.augmented	Manufacturer Part Number: TS836-4IPT
	Manufacturer/Brand: STMicroelectronics
	Part of Description: IC SUPERVISOR VOLT RESET 8-TSSOP
	Datasheets:  TS836-4IPT.pdf
RoHs Status:  Lead free / RoHS	Stock Condition: Compliant New original, Stock Available.
Ship From: Hong Kong	Shipment Way: DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

Specifications

Part Number	TS836-4IPT
Manufacturer	STMicroelectronics
Description	IC SUPERVISOR VOLT RESET 8-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	8-TSSOP
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	20 µs Typical Response Time
Voltage - Threshold	4.5V
Packaging	Tape & Reel (TR)

TS836-4IPT is New Original in Stock, Search TS836-4IPT Datasheets, PDF, Inventory at Y-IC.com Online, Order TS836-4IPT STMicroelectronics with warrantied and confidence. RFQ TS836-4IPT : Info@Y-IC.com

You May Be Also Be interested

In:

 TS836-4IZ STMicroelectronics IC SUPERVISOR VOLT RESET TO-92	 TS834-5ID STMicroelectronics IC SUPERVISOR VOLT RESET 8-SOIC	 TS834-5IPT STMicroelectronics IC SUPERVISOR RESET 4.33V 8TSSOP	 TS836-4IDT STMicroelectronics IC SUPERVISOR VOLT RESET 8-SO
 TS836-4IZ-AP STMicroelectronics IC SUPERVISOR VOLT RESET TO-92	 TS836-4ID STMicroelectronics IC SUPERVISOR VOLT RESET 8-SO	 TS836-4IZT STMicroelectronics IC SUPERVISOR VOLT RESET TO-92	 TS83C51RB2-MA TEMIC TEMIC TQFP44

Hot Parts

More

- | | | | | |
|-----------------|----------------|--------------------|----------------------|----------------------|
| ADG609BR-REEL | AON6910A | AP20T03GH-1 | BCM3440KQTE | BR93C46-10SU1.8 |
| BstP6486K | BYG21M-E3/TR3 | BZG05C12TR3 | CGA5L2X8R1E105K160AE | CGA8L2X7R1E475M160KA |
| CL43B106MALNNNF | CS49844A-CQZ | DB2U30900L | DD231N12 | EMA2004-50MA08GRR |
| FHB1132R-E | FOD3184SD | GRM2165C1H821JA01J | GRM2197U2A5R1DD01D | IRFS11N50A |
| IRS2332JTRPBF. | ISO7760FDWR | IXTQ96N15P | KSA1381ES | L-7104ID |
| LQP02TN5N1S02D | LQW31HN15NJ01L | LTC1261LCMS8#TRPBF | LTV-217-C-G | MBR20H100CTG |
| MIC5377YMT | NSM80100MT1G | PD110F120 | PD230S16 | QMK325BJ154KN-T |
| S-8253AAC-T8T1S | SDR0602-470K | SFH6755T | SIP21106DR-28-E3 | SKDH150/16 |
| SKFH150/08DT | SKT1000/12E | SN74HCT74N | T318F08TSL | TL431SN3 |
| TLV3402CDRG4 | TPS79901DRVR | TS5A4594DBVRG4 | USS5350L-AB3-R | XC6219A332MR-G |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited