

	MMA6821AKWR2	
	Manufacturer Part Number:	MMA6821AKWR2
Manufacturer/Brand:	FREESCA	
Part of Description:	FREESCA QFN	
RoHs Status:		
Stock Condition:	New original, 900 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications	
Part Number	MMA6821AKWR2
Manufacturer	FREESCA
Description	FREESCA QFN
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	900 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MMA6821AKWR2 is New Original in Stock, Search MMA6821AKWR2 Datasheets, PDF, Inventory at Y-IC.com Online, Order MMA6821AKWR2 with warrantied and confidence. RFQ MMA6821AKWR2 : Info@Y-IC.com

You May Be Also Be interested

In:

 MMA6821AKGWR2 NXP Semiconductors / Freescale ACCELEROMETER 10BIT SPI 16QFN	 MMA6813KW FREESCA FREESCA (QFN-16)	 MMA6821BKCWR2 NXP Semiconductors / Freescale ACCELEROMETER 10BIT SPI 16QFN	 MMA6821BKWR2 NXP Semiconductors / Freescale ACCELEROMETER 120G/25GSPi 16QFN
 MMA6821BKW NXP Semiconductors / Freescale ACCELEROMETER 120G/25GSPi 16QFN	 MMA6821AKGCWR2 NXP Semiconductors / Freescale ACCELEROMETER 10BIT SPI 16QFN	 MMA6821AKW NXP Semiconductors / Freescale ACCELEROMETER 16QFN	 MMA6813KWR2 NXP Semiconductors / Freescale ACCELEROMETER 50G 16QFN

Hot Parts More

- | | | | | |
|----------------------|-------------------|-------------------------|--------------------|------------------------|
| ⚙️ 0201YA680JAT2A | ➡️ 08055A151K4T2A | ➡️ 1808SC681KAT1A | D 2743021447 | ➡️ 7MBR10SG120 |
| ⚡ AD9865BCPZRL | ⚙️ AEE02A48 | D AM80A-048L-240F10 | ➡️ AP4413GM | ➡️ BA25BC0FP-E2 |
| ⚙️ BYV27-600-TAP | ⚡ BZM55B5V1-TR | ⚙️ CKCA43X7R1C104MT010N | ➡️ DMP2069UFY4-7 | ➡️ EVK105RH2R4JW-F |
| D FDS6375-NL | ⚙️ GBLC18-LF-T7 | ⚡ HCPL2731SD | ⚙️ HMPP-3895-TR1G | ➡️ HP50410091R0-043211 |
| ➡️ IRLR9343TRR | ➡️ KIA78D06F-RTF | ⚙️ LT1952EGN-1#PBF | ⚡ LTC1435AIS#TRPBF | ➡️ LTC3456EUF#TRPBF |
| ➡️ LTC4415EMSE#TRPBF | ➡️ M24512-WMN6P | D MAX3483ECSA+T | ⚙️ MAX5940CESA | ⚡ MBR1550CT |
| ⚙️ MIC2551YML | D N282CH22 | ➡️ PE160F-80 | ➡️ PF38F4060L0YUE | ➡️ PM19T3REH501GNE-OT |
| ⚡ PS1117G-5.0-T43R | ⚙️ RT9261A-33PB | ➡️ S-1701E3026-M5T1G | ➡️ SCV303LSN46T1 | ➡️ SG2524BN |
| ⚙️ SKM500GA123DS | ⚡ SM6451AV-E2 | ⚙️ SN25PCR134 | D SY88403BLEY | ➡️ T860N34TOC |
| ➡️ TC74LCX07FT | ⚙️ TL1084CZ | ⚡ TMK063CH330JT-F | ⚙️ TT250N06KOF | ➡️ UPA2816T1S-E2-AT |