



 A Renesas Company	ISL6398IRTZ-T
	Manufacturer Part Number: ISL6398IRTZ-T
	Manufacturer/Brand: Intersil
	Part of Description: IC REG CTRLR BUCK PMBUS 40TQFN
Datasheets:	 1.ISL6398IRTZ-T.pdf
	 2.ISL6398IRTZ-T.pdf
RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	









Specifications

Part Number	ISL6398IRTZ-T
Manufacturer	Intersil
Description	IC REG CTRLR BUCK PMBUS 40TQFN
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Output Type	PWM Signal
Package / Case	40-VFQFN Exposed Pad
Supplier Device Package	40-TQFN (5x5)
Function	Step-Down
Frequency - Switching	120kHz ~ 2.025MHz
Number of Outputs	6
Output Configuration	Positive
Voltage - Supply (Vcc/Vdd)	4.75 V ~ 5.25 V
Topology	Buck
Control Features	-
Output Phases	6
Duty Cycle (Max)	98%
Synchronous Rectifier	No
Clock Sync	-
Serial Interfaces	I ² C, PMBus, SMBus
Packaging	Tape & Reel (TR)

ISL6398IRTZ-T is New Original in Stock, Search ISL6398IRTZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6398IRTZ-T Intersil with warrantied and confidence. RFQ
ISL6398IRTZ-T : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL6398IRTZ Intersil IC REG CTRLR BUCK PMBUS 40QFN	 ISL6401CBZ Intersil IC REG CTRLR BOOST/FLYBK 14SOIC	 ISL6401CB-T Intersil IC REG CTRLR BOOST/FLYBK 14SOIC	 ISL6398HRTZ-TK Intersil IC REG CTRLR BUCK PMBUS 40QFN
 ISL6388IRTZ-T Intersil IC CTRLR PWM 6PHASE BUCK 40QFN	 ISL6398HRTZ-T Intersil IC REG CTRLR BUCK PMBUS 40QFN	 ISL6401CBZ-T Intersil IC REG CTRLR BOOST/FLYBK 14SOIC	 ISL6398IRTZ-TK Intersil IC REG CTRLR BUCK PMBUS 40QFN

Hot Parts

More

- | | | | | |
|-----------------------|-----------------------|------------------|-------------------|-------------------|
| ⊛ 0603YC472KAT2A | ↔ 08051C510KAT2A | ⇒ ADR96S1100KFC | D AP1682MTR-G1 | ⇒ AT636S16 |
| ⊣ AU5517DR2G | ⊛ AZ1085T-5.0E1 | D B82422H1102K | ⇒ BD244BTU | ⇒ BXA3-12S05 |
| ⊛ C1608X6S1V474M080AB | ⊣ C2012C0G2E392K125AA | ⊛ CAT25128XI-T2 | ↔ CL05B102KO5NNNC | ⇒ DKW2412D-5W |
| D FDP13AN06A0 | ⊛ HMHA281R1V | ⊣ HWMZ9023306PSC | ⊛ IRG4IBC30FDPBF. | ⇒ L18P46R7D12/TS |
| ⇒ LM1117MP-3.3 | ↔ MAC228A6 | ⊛ MM502-LF | ⊣ MMSZ5239BT/R | ⇒ OPA4364AIDG4 |
| ↔ P20NM50FD | ⇒ PF1206FRM7WR01 | D PM8801TR | ⊛ PS21244-B03 | ⊣ R3064XL-10CS48C |
| ⊛ RB168LAM-30TF | D RJK0213DPA-00-J53 | ⇒ SAB-C510-R8N | ↔ SG2525AN | ⇒ SKY77425-16 |
| ⊣ SMAJ150A-E3/61 | ⊛ SN74ABT16374ADLR | ↔ STL66N3LLH5 | ⇒ SY88973VKI | ⇒ T6201420 |
| ⊛ TCA14AR-W1 | ⊣ TMCMC0J476M | ⊛ TPS65132LYFFR | D UCC38050DRG4 | ⇒ V300B12C250BG |
| ↔ V48C3V3C75A002 | ⊛ VI-2T2-CX | ⊣ VSKH91/16P | ⊛ VU082-16N07 | ⇒ XRT73LC03AIV-F |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited