


	<p>S-1000C17-N4T1G</p>
	<p>Manufacturer Part Number: S-1000C17-N4T1G</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 17V SC-82AB</p>
<p>Image may be representation. See specs for product details.</p>	<p>Datasheets:  S-1000C17-N4T1G.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-1000C17-N4T1G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 17V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-1000
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	1.7V
Packaging	Tape & Reel (TR)

S-1000C17-N4T1G is New Original in Stock, Search S-1000C17-N4T1G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-1000C17-N4T1G SII Semiconductor Corporation with warrantied and confidence. RFQ S-1000C17-N4T1G : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-1000C18-M5T1G SII Semiconductor Corporation IC VOLT DETECTOR 18V SOT23-5</p>	 <p>S-1000C16-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1000C17-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR 17V SNT-4A</p>	 <p>S-1000C17-I4T1G SII Semiconductor Corporation IC VOLT DETECTOR 17V SNT-4A</p>
 <p>S-1000C17-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1000C18-I4T1G SII Semiconductor Corporation IC VOLT DETECTOR 18V SNT-4A</p>	 <p>S-1000C17-M5T1G SII Semiconductor Corporation IC VOLT DETECTOR 17V SOT23-5</p>	 <p>S-1000C18-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR 18V SNT-4A</p>

Hot Parts

More

- | | | | | |
|-----------------------|----------------------|-----------------------|---------------------|-------------------------|
| ⊛ 0603ZA2R7JAT2A | ↔ 12067C332JAT2A | ⇒ 7MBR10SA120J | D 91MT160KPBF | ⇒ AD8356AS2P |
| ⊣ ADP1712AUJZ-R71 | ⊛ AIC1117PYTR | D AP8600MT | ⇒ AT32UC3B0512-Z2UR | ⇒ B30811-D5102-Y313-W03 |
| ⊛ BA5934FP-E2 | ⊣ BBY58-03WE6327 | ⊛ C3216NP02A223J160AA | ↔ CAT22C10ZIT-30 | ⇒ DG211BDQ-T1-E3 |
| D DM74ALS540AWMX | ⊛ DSEK60-02 | ⊣ ES2CA-13-F | ⊛ FGA15N120ANTDTU | ⇒ FQD7N10LTF |
| ⇒ GRM1555C1H2R3WZ01D | ↔ IR3084UMTRPBF | ⊛ ISA1235AC1-T112A-1F | ⊣ LMSW43TA-694 | ⇒ LMV393IDGKR |
| ↔ LP2975AIMMX-12/NOPB | ⇒ LP3874EMP-2.5 | D LT1085CM#TR | ⊛ LT1764ET | ⊣ MBRP40020CT |
| ⊛ MC14016BDR2 | D P4KE20CA | ⇒ QFEM-7782-TR1 | ↔ R0830LS10F | ⇒ RB068L-60DDTE25 |
| ⊣ RTD14048 | ⊛ S5K6A1GX04 | ↔ SI3051NA | ⇒ SM08CXC190 | ⇒ SN761673DAERG4 |
| ⊛ SP3239ECA | ⊣ SP481REP | ⊛ STK2139AN6G | D T6250340 | ⇒ THS4271MDGNREP |
| ↔ TLC2272CD | ⊛ TLV320AIC3006IZQER | ⊣ TMK316B3475ML-T | ⊛ VUO82-12N07 | ⇒ XRT83SL34IV-F |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited