	<p><b>EL1506CM-T13</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">EL1506CM-T13</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC LINE DRVR DUAL ADSL 24SO</p> <p><b>Datasheets:</b> <a href="#">EL1506CM-T13.pdf</a></p> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <p><b>Stock Condition:</b> New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









### Specifications

Part Number	EL1506CM-T13
Manufacturer	Intersil
Description	IC LINE DRVR DUAL ADSL 24SO
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Driver
Package / Case	24-SOIC (0.295", 7.50mm Width)
Supplier Device Package	24-SO
Voltage - Supply	5 V ~ 12 V
Protocol	DSL
Number of Drivers/Receivers	2/0
Duplex	-
Data Rate	-
Packaging	Tape & Reel (TR)

EL1506CM-T13 is New Original in Stock, Search EL1506CM-T13 Datasheets, PDF, Inventory at Y-IC.com Online, Order EL1506CM-T13 Intersil with warrantied and confidence. RFQ EL1506CM-T13 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>EL1506CRE-13</b> INTERSIL EL1506CRE-13 INTERSIL</p>	 <p><b>EL1506CRE-T13</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP</p>	 <p><b>EL1506CRE</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP</p>	 <p><b>EL1503CM-T13</b> ISL EL1503CM-T13 ISL</p>
 <p><b>EL1503CMAAU</b> ELANTE EL1503CMAAU ELANTE</p>	 <p><b>EL1503CM</b> Original EL1503CM Original</p>	 <p><b>EL1506CREZ</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP</p>	 <p><b>EL1503CL-T7</b> ELANTEC EL1503CL-T7 ELANTEC</p>

### Hot Parts

[More](#)

- |                        |                              |                    |                      |                      |
|------------------------|------------------------------|--------------------|----------------------|----------------------|
| 08051U100JAT2A         | 1-282042-5                   | 12105C154KAT2A     | D 1808AC100KAT9A     | 1812WC332KAT1A\SB    |
| 1SMB5921B-13           | 45-21S/KK2C-S5757L1L4B2Z3/2T | D AD9750ARURL7     | B39431-B3710-U410    | BDX54ATU             |
| BQ24030RHLR            | BTB16-600BRG                 | BYM11-200-E3/96    | CEU4J2X7R1H223M125AE | CGA4J3X8R2A683K125AB |
| D CGA5L3X8R2A334M160AE | DCR508ST0911                 | DS1302Z+TR         | DTC124EL             | F0505S-1W            |
| FDS6892AZ-NL           | GRM1886S1H7R4DZ01D           | GSD2004S-E3-08     | LD055C103JAB2A       | LF411ACN/NOPB        |
| LP2987IM-2.8           | MBRD320RL                    | D MG150Q1JS44A     | MIC5319-2.6YD5TR     | NCP1117ST25T3G       |
| NDS332P-NL             | NR3012T6R8M                  | P87C54X2BDH        | PMEG3015EV           | PS21313-B6           |
| PSB83524M              | QMJ325B7224KNHT              | RT3T66M-T111-1     | S1D13714B00B10B      | SBR1040CTFP          |
| SI2336DS-T1-GE3        | SKKE81/08E                   | SMM02040C3013FB300 | D TC59LM814CTG-50    | TL7702AIDRG4         |
| TS2937CM12             | UMK212SD822KD-T              | VE-J33-CY          | VI-J1L-CX            | YW1512U              |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited