


	<h2 style="color: #E67E22;">LB1930MC-BH</h2>
	Manufacturer Part Number: LB1930MC-BH
	Manufacturer/Brand: AMI Semiconductor / ON Semiconductor
	Part of Description: IC MOTOR DRIVER PAR 10SOIC
	Datasheets:  LB1930MC-BH.pdf
	RoHS Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
Ship From: Hong Kong	
Shipment Way: DHL/Fedex/TNT/UPS/EMS	

Specifications

Part Number	LB1930MC-BH
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC MOTOR DRIVER PAR 10SOIC
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	Require For Quote & Check Stock
Series	-
Technology	Bipolar
Operating Temperature	-30°C ~ 85°C (TA)
Mounting Type	Surface Mount
Interface	Parallel
Applications	Media Player
Package / Case	10-SOP (0.154", 3.90mm Width)
Supplier Device Package	10-SOIC
Voltage - Supply	2.2 V ~ 10.8 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	1A
Output Configuration	Half Bridge (2)
Voltage - Load	2.2 V ~ 10.8 V
Motor Type - Stepper	-
Motor Type - AC, DC	Brushed DC
Step Resolution	-
Packaging	Tape & Reel (TR)

LB1930MC-BH is New Original in Stock, Search LB1930MC-BH Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1930MC-BH AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LB1930MC-BH : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>LB1930MGEVB AMI Semiconductor / ON Semiconductor BOARD EVAL FOR LB1930M</p>	 <p>LB1930M-TLM SANYO LB1930M-TLM SANYO</p>	 <p>LB1933 SANYO LB1933 SANYO</p>	 <p>LB1931T-A-TLM SANYO SANYO MSOP8</p>
 <p>LB1930M-MPB-H SANYO LB1930M-MPB-H SANYO</p>	 <p>LB1930MCGEVB AMI Semiconductor / ON Semiconductor BOARD EVAL FOR LB1930MC</p>	 <p>LB1930M SANYO LB1930M SANYO</p>	 <p>LB1930MC-AH AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 10SOIC</p>

Hot Parts

More

- | | | | | |
|------------------|---------------------|--------------------|------------------------|--------------------|
| ⊛ 0603YC682KAT2A | ↔ 08053D106MAT2A | ⇒ 24LC08B-I/MS | D 2MBI300U4H120-50 | ⇒ 2N6575G. |
| ⊖ 6MBP300KA-60 | ⊛ AD5241BRZ10 | D ADM6999X-A2-T-1 | ⇒ AGQ260A12 | ⇒ AT25256-10TI-2.7 |
| ⊛ BD6719FV-E2 | ⊖ CAT6217-250TDGT3 | ⊛ CAT812STBI-T | ↔ CEU3E2X7R2A332M080AE | ⇒ ELM9830AA-S |
| D ES1PC-E3/84A | ⊛ FDH300A.TR | ⊖ FDMS3672 | ⊛ FDN339AN | ⇒ FF800R16 |
| ⇒ FOD814ASD | ↔ FPC2050BP-1B-CP01 | ⊛ ICS9248AG-198LFT | ⊖ INA139QPWRQ1 | ⇒ IRF7425TRPBF |
| ↔ JW150F-42 | ⇒ KS625540A41 | D LD055A102GAB2A | ⊛ LM358DGKR | ⊖ LT1175CS8#TRPBF |
| ⊛ LT1355CN8 | D MAX1917EEE+T | ⇒ MAX4666CSE-T | ↔ OPA2345UA/2K5 | ⇒ PBSS5260PAP |
| ⊖ PKA4211PI | ⊛ PTZTE258.2B | ↔ R920242000 | ⇒ RC0603FR-073KL | ⇒ SI4178DY-T1-E3 |
| ⊛ SI6469DQ-T1 | ⊖ SM6A27-6600E3/2D | ⊛ SMCJ130A-E3/57T | D SNB-1200-0.47-T250 | ⇒ SP3243EUCA-L/TR |
| ↔ SP6260FEK-L/TR | ⊛ SZMMSZ5263BT1G | ⊖ TR/3216FF-1A | ⊛ TUSB522PIRGER | ⇒ XCS10XL-VQ100AKP |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited