










	PI49FCT805ATHE	
	Manufacturer Part Number:	PI49FCT805ATHE
	Manufacturer/Brand:	Diodes Incorporated
	Part of Description:	IC CLK BUFFER 1:5 66MHZ 20SSOP
	Datasheets:	 PI49FCT805ATHE.pdf
	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
	Shipment Way:	DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.		

Specifications

Part Number	PI49FCT805ATHE
Manufacturer	Diodes Incorporated
Description	IC CLK BUFFER 1:5 66MHZ 20SSOP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	49FCT
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	66MHz
Package / Case	20-SSOP (0.209", 5.30mm Width)
Supplier Device Package	20-SSOP
Number of Circuits	2
Voltage - Supply	4.75 V ~ 5.25 V
Output	CMOS
Input	CMOS, TTL
Ratio - Input:Output	1:5
Differential - Input:Output	No/No
Packaging	Tube

PI49FCT805ATHE is New Original in Stock, Search PI49FCT805ATHE Datasheets, PDF, Inventory at Y-IC.com Online, Order PI49FCT805ATHE Diodes Incorporated with warrantied and confidence. RFQ PI49FCT805ATHE : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>PI49FCT805ATS Diodes Incorporated IC CLK BUFFER 1:5 66MHZ 20SOIC</p>	 <p>PI49FCT805ATQ Diodes Incorporated IC CLK BUFFER 1:5 66MHZ 20QSOP</p>	 <p>PI49FCT805ATQE Diodes Incorporated IC CLK BUFFER 1:5 66MHZ 20QSOP</p>	 <p>PI49FCT3807SC Pericom Semiconductor Corp. (Diodes Incorporated) PI49FCT3807SC PERICOM</p>
 <p>PI49FCT3807SE Diodes Incorporated IC CLK BUFFER 1:10 50MHZ 20SOIC</p>	 <p>PI49FCT3807QX PERICOM PI49FCT3807QX PERICOM</p>	 <p>PI49FCT805ATQX PERICOM PI49FCT805ATQX PERICOM</p>	 <p>PI49FCT804ATS Diodes Incorporated IC CLK BUFFER 1:4 66MHZ 16SOIC</p>

Hot Parts

More

- | | | | | |
|---------------------|--------------------------|--------------------------|-------------------------|---------------------|
| ⚙️ 08051A270KAT2A | ➡️ 13024R1A | ➡️ AD9648BCPZRL7-125 | D ADP3339AKC-3.3-RL7 | ➡️ AP6904GH-HF |
| ⚡ B360A-E3/61T | ⚙️ BTA12-600CRG | D CDBK0520-HF | ➡️ CGA9N2X7R2A225K230KA | ➡️ E2000NH170 |
| ⚙️ FSA9485UCX | ⚡ FSBS5CH60F | ⚙️ GL4800E0000F | ➡️ IXGQ28N120B2D | ➡️ IXSK35N120AU1 |
| D LT3080EMS8E-1#PBF | ⚙️ LTC1842IS8#TRPBF | ⚡ LTC4151IMS-1 | ⚙️ LTC6652AHMS8-2.5#PBF | ➡️ MAX1910EUB |
| ➡️ MC-7950-E1 | ➡️ MJE18004D2G | ⚙️ MT41J128M16HA-125IT:D | ⚡ NTR4170NT1G | ➡️ P4SMAJ22A |
| ➡️ PI74ALVCH16646A | ➡️ PKF4117ASI | D PS2532L-1-E3 | ⚙️ QBD070ZHH-A1H | ⚡ QM2A1UA004/EL |
| ⚙️ SA1117BH-3.3TR | D SC4205IS-2.5TRT | ➡️ SCH2806-TL-E | ➡️ SGB2433Z | ➡️ SKKT250/12 |
| ⚡ SP102164M | ⚙️ SPX5205M5-L-2.8/TR | ➡️ STD091M08M | ➡️ STR751FR2T6 | ➡️ SUD45P03-09-E3 |
| ⚙️ T3159N24TOF | ⚡ TA48S025AF | ⚙️ TCA1A106M8R | D TCLL26V2 | ➡️ TMP47C400AF-6547 |
| ➡️ TPS22994RUKR | ⚙️ UPD78F0501MC-5A4-E1-A | ⚡ V24C5H100A | ⚙️ W25Q64FVZPIG | ➡️ XC61FN2712MRN |

Contact us: **Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited