









	<h2 style="color: #E67E22;">ZL40210LDF1</h2>	
	Manufacturer Part Number:	ZL40210LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFF MUX 2:8 750MHZ 32QFN
	Datasheets:	1.ZL40210LDF1.pdf 2.ZL40210LDF1.pdf 3.ZL40210LDF1.pdf
<p>Image may be representation. See specs for product details.</p>	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
Shipment Way:		DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	ZL40210LDF1
Manufacturer	Microsemi
Description	IC CLK BUFF MUX 2:8 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution), Multiplexer
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	2:8
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40210LDF1 is New Original in Stock, Search ZL40210LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40210LDF1 Microsemi with warrantied and confidence. RFQ
ZL40210LDF1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ZL40207LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40208LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40209LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40212LDF1 Microsemi IC CLK BUFFER 1:2 750MHZ 16QFN</p>
 <p>ZL40211LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40210LDG1 Microsemi IC CLK BUFF MUX 2:8 750MHZ 32QFN</p>	 <p>ZL40208LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40209LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>

Hot Parts

More

# 12061A5R1CAT2A	↔ ADG201HSKN	⇒ AP78L12YG-13	D BC856BLT1G	⇒ BCM53346A0KFSBG
↳ C0402C0G1C160J	# C2012X7R1E474KT00N	D CC603JRNPO09BN560	⇒ CDSOT23-T15LC	⇒ CL10C050BB8NFNC
# DMP1081UCB4	↳ DRQ74-3R3-R	# DS90UB914QSQ/NOPB	↔ EL51061WZ-T7	⇒ ELM9718CBA
D GRM188R60J105KA01J	# HVC300ATRU-EQ	↳ IRF7811WTRPBF	# IRKT133-14S90	⇒ KK2800A1800V
⇒ LC1472CB5TR30	↔ LP2985AIBL-1.8	# LQW04AN8N2C00D	↳ MB15F03PFV1-G-BND-EF	⇒ MB95F818KPMC-G-SNE2
↔ MBF21M2450H133	⇒ MDSB60B-16	D MG75G2YK1	# ML03511R9BAT2A	↳ MP1605GTF-Z
# N0882NC450	D NCP563SQ15T1G	⇒ ND260N20K	↔ PAH150S48-12	⇒ PC4D100NIP0F
↳ PM400HV-34S	# RT8096CHGB	↔ RT8237AGQW	⇒ S-80933CNPF-G83TFG	⇒ SAA7372GP
# SAB80268	↳ SC112CSK-3.8.TR	# SEMIX103GB126HD	D SIP21110DT-T1-E3	⇒ SKIIP39ANB16V1
↔ SKT40/10	# ST173CPBF	↳ TLA-3T110LF-T	# TPS79730QDCKRQ1	⇒ VUO60-12NO3

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited