

 <p>Not Actual Photo YIC International Co., Limited.</p>	<p>SSF9N80</p>
	<p>Manufacturer Part Number: SSF9N80</p> <p>Manufacturer/Brand: FSC</p> <p>Part of Description: FSC TO-3P</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 16700 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	SSF9N80
Manufacturer	FSC
Description	FSC TO-3P
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	16700 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

SSF9N80 is New Original in Stock, Search SSF9N80 Datasheets, PDF, Inventory at Y-IC.com Online, Order SSF9N80 with warranted and confidence. RFQ SSF9N80 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>SSF7509 SILIKRON SILIKRON TO-220</p>	 <p>SSF9926 VB VB SOP-8</p>	 <p>SSF7N60B FSC SSF7N60B FSC</p>	 <p>SSF8205A SSF SSF TSSOP8</p>
 <p>SSFC10AR12A4-10A SOC SSFC10AR12A4-10A SOC</p>	 <p>SSFC1AR12A4 SOC SOC SMD1808</p>	 <p>SSFC10AR12A4 50A 125V SOC SOC SMD</p>	 <p>SSFC1A SOC SOC SMD</p>

Hot Parts

More

- | | | | | |
|--------------------|------------------------|--------------------|----------------------|----------------------|
| ⊛ 06031A8R2C4T2A | ↔ 12065A271JAT2P | ⇒ 12101C104JAT2A | D 1812HC471MAT1A | ⇒ 2225AA222MAT1A\SB |
| ⊣ A2982SLWT | ⊛ AFP3401ASS23RG | D BC859-B-RTK/P | ⇒ BD9251FV-E2 | ⇒ CC0805JRNPO9BN151 |
| ⊛ CDC2509CPWR | ⊣ CGA3E2COG1H150J080AD | ⊛ CS400-18io2 | ↔ DS90UR905QSQE/NOPB | ⇒ DTC114WSATP |
| D FCD850N80Z | ⊛ GRM1555C1H7R5DA01D | ⊣ HCB1608K-242JT | ⊛ HGTG20N60A4 | ⇒ INA159AIDKR |
| ⇒ LT3090IMSE#TRPBF | ↔ LT3092ETS8#TRPBF | ⊛ LTC1452CS8#TRPBF | ⊣ M29W320EB70ZE6E | ⇒ MADP-007437-0287FT |
| ↔ MIC2009YM6 | ⇒ MIC5213-2.8YC5TR | D NJV4030PT1G | ⊛ PRDMB75B17A9 | ⊣ PWB100A20 |
| ⊛ RT9595GQW | D SBR20A100CT-G | ⇒ Si9410ADY-T1-GE3 | ↔ SK40GAL067 | ⇒ SKN130/12 |
| ⊣ SMBH1G200US60 | ⊛ SMBJ70CA | ↔ SMF78A_R1_00001 | ⇒ SN74LVC2T45YZPRB | ⇒ SPP04N60S5 |
| ⊛ STB22NE10LT4 | ⊣ TLE428L2 | ⊛ TPS40304DRCR | D UC2844DR2G | ⇒ V24B28H200BL3 |
| ↔ V8P12-M3/87A | ⊛ VI-B00-EX | ⊣ VI-JT3-IX | ⊛ VIPER06LN | ⇒ X9269US24IZ-2.7 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited