

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">TC4S01F(TE85R)</h2>
	<p>Manufacturer Part Number: TC4S01F(TE85R)</p> <p>Manufacturer/Brand: TOSHIBA</p> <p>Part of Description: TOSHIBA SOT-153</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 3500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	TC4S01F(TE85R)
Manufacturer	TOSHIBA
Description	TOSHIBA SOT-153
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	3500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

TC4S01F(TE85R) is New Original in Stock, Search TC4S01F(TE85R) Datasheets, PDF, Inventory at Y-IC.com Online, Order TC4S01F(TE85R) with warrantied and confidence. RFQ TC4S01F(TE85R) : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>TC4S11F(F) TOSHIBA TC4S11F(F) TOSHIBA</p>	 <p>TC4S01F T5L,F,T TOSHIBA TOSHIBA SOT153</p>	 <p>TC4S11F(TE85L,F) TOSHIBA TC4S11F(TE85L,F) TOSHIBA</p>	 <p>TC4S01F(TE85L,F) TOSHIBA TC4S01F(TE85L,F) TOSHIBA</p>
 <p>TC4S01F(TE85L) TOSHIBA TOSHIBA SOT153</p>	 <p>TC4S01F T5L TOSHIBA TOSHIBA SOT153</p>	 <p>TC4S11F TOSHIBA TC4S11F TOSHIBA</p>	 <p>TC4S01F-TE85R TOSHIBA TC4S01F-TE85R TOSHIBA</p>

Hot Parts

More

- | | | | | |
|---------------------|------------------------|------------------------|-------------------------|-------------------|
| ⚙️ 06035A510JAT2A | ➡️ 1812CC332KATME | ➡️ 7MBR35VM120 | D AC0402FR-7W120RL | ➡️ AD8123ACPZ-R7 |
| ⚡️ ADG509FBRN | ⚙️ BD240CTU | D BSC100N10NS | ➡️ BSM75GB170DLC | ➡️ BZM55B4V3 |
| ⚙️ C0402C0G1C1R2B | ⚡️ C1608C0G2A222K080AA | ⚙️ C3216X8R1H105K160AE | ➡️ CGJ2B2C0G1H101J050BA | ➡️ DAC6574IDGSR |
| D DB2730800L | ⚙️ DD90F.40 | ⚡️ DT56N1400KOF | ⚙️ EE-SX670-WR | ➡️ FCA50CC50 |
| ➡️ FM16W08-SG | ➡️ FM25V20-GTR | ⚙️ GRM1885C1H6R2DZ01D | ⚡️ HHM1525S1 | ➡️ HIP2100IRZT |
| ➡️ KC70E1E226M-TS | ➡️ LC78604E-E | D LD2981ABM28TR | ⚙️ MAX4772EUT-T | ⚡️ MBRB7H50-E3/31 |
| ⚙️ MIC5331-G4YMT | D MP4000DS-C407-LF-Z | ➡️ NL37WZ17US | ➡️ NNCD6.2MF-T1B | ➡️ NVD20N03L27T4G |
| ⚡️ OPA842IDBVR | ⚙️ RA2F3610AS | ➡️ RJK0349DPA-00-J0 | ➡️ SCH5514D-NS | ➡️ SM5021KDH-G-EL |
| ⚙️ SM6T10CA-TR | ⚡️ SMV1251-001 | ⚙️ SS10P3CL-M3/86A | D T1078F02TCL | ➡️ TPS3106E09DBVT |
| ➡️ TZC03R100A310T00 | ⚙️ VI-HAMD-EM-02 | ⚡️ VI-J21-MZ | ⚙️ VI-JT1-EY-02 | ➡️ ZS61205 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited